

Additional Funding Request

MD003	CSS# 28548 WO# 13609 Asset# NA							
Description of Repairs	S&S proposes to complete the following: S&S will remove and replace the inducer motor, fuse block and fuses. S&S will then complete a system check to ensure everything is running properly.							
Diagnosis: Initial Work Order	There is no heat in the drill hall. The units for the drill hall are not linked to the center boilers and are standalone units. Not sure why they are not maintaining temp, but they were running during my visit. The interior set point was 68, and the interior temp was 61. The units are running but not heating. Need to have troubleshoot and repaired.							
Diagnostic Fee	\$ 350 Labor \$100/hr x 3.5							
Additional Labor Cost to Perform Repairs	\$ 1000 Labor \$100/hr x 10							
Additional Material Cost to Perform Repairs	\$ 745.94 <table border="1"><tr><td>Parts</td><td>1</td><td>745.94</td><td>745.94</td></tr></table>				Parts	1	745.94	745.94
Parts	1	745.94	745.94					
Total Cost of Repair	\$ 2095.94							

**S&S MECHANICAL****S&S Mechanical**
4831 South Crain Highway
Upper Marlboro, MD 20772Tel. 1 - (301) 574-1555
Fax. 1 - (301) 574-1558
www.sandsmidatlantic.com**CUSTOMER QUOTATION NO. 494**Tidewater, Inc.
Tidewater, Inc
6625 Selnick Dr.
Suite A
Elkridge MD 21075**Quote Name:** 13609
Quote No: 494
Site: MD003 Liberty Heights
Site Contact:
Salesperson: Lindsay Ruby
Created Date: 01/22/2021
Valid For: 30 Day(s)**WO#: 13609****CSS Ticket Number: 28548**

SOW: There is no heat in the drill hall. The units for the drill hall are not linked to the center boilers and are standalone units. Not sure why they are not maintaining temp, but they were running during my visit. The interior set point was 68, and the interior temp was 61. The units are running but not heating.

S&S herby proposes to complete the following:

S&S will remove and and replace the inducer motor, fuse block and fuses.

S&S will then complete a system check to ensure everything is running properly.

Service

Item	Quantity	Unit Price	Total
VENTOR ASSY/ 216196	1.00	\$600.58	\$600.58
Fuse Box	1.00	\$36.00	\$36.00
Fuse/74975384	2.00	\$4.68	\$9.36
Shipping	1.00	\$100.00	\$100.00
Diagnosis Fee	1	\$350.00	\$350.00
HVAC Labor Rate	10	\$100.00	\$1,000.00
Sub-Total ex Tax			\$2,095.94
Tax			\$0.00
Total inc Tax			\$2,095.94

Labor	\$1,350.00
Materials	\$745.94
Sub-Total ex Tax	\$2,095.94
Tax	\$0.00
Total inc Tax	\$2,095.94



JOHNSTONE SUPPLY THE BALSAN GROUP

JOHNSTONE ANNAPOLIS
1981 MORELAND PKWY, SUITE 101
ANNAPOLIS, MD 21401
410-280-0101
Fax 410-280-0104

Quotation

EXPIRATION DATE	QUOTE NUMBER
03/23/2021	100-100948537
JOHNSTONE ANNAPOLIS 1981 MORELAND PKWY, SUITE 101 ANNAPOLIS, MD 21401 410-280-0101 Fax 410-280-0104	PAGE NO. 1 of 1

QUOTE TO:

SHIP TO:

S&S MECHANICAL
4845 SOUTH CRAIN HIGHWAY
UPPER MARLBORO, MD 20772

S&S MECHANICAL
4845 SOUTH CRAIN HIGHWAY
UPPER MARLBORO, MD 20772

CUSTOMER NUMBER	CUSTOMER PO NUMBER	JOB NAME / RELEASE NUMBER	SALESPERSON		
14831	MD003 WO# 13609	145087	HOUSE		
WRITER		SHIP VIA	TERMS	SHIP DATE	FREIGHT ALLOWED
Jimmy Schropp - Anna 43		PICK UP	Net 10th Prox	01/22/2021	No
ORDER QTY	DESCRIPTION			UNIT PRICE	EXT PRICE
1ea	5H0767230002 208/230V VENTOR ASSY * Non Returnable / Non refundable Pn: 216196			500.477/ea	500.48

Quotation Valid For 20 Days.

Subtotal	500.48
S&H Charges	40.00
Estimated Tax	30.03
Amount Due	570.51

FASCO

No. 702110898

TYPE U21E

Assembled in Mexico

115 V

2.0 A

60 Hz

3000 RPM

Coil PIN 5H0767230001

Switch 125VA-120V



T.P. Class B

LR36496

SW280-1

Connection Diagram

Blk — Line

Wht — Line

Orn —

Orn —

AO
M3410