

Additional Funding Request
INVOICE

MD024	CSS# 28563 WO# 13612 Asset# NA							
Description of Repairs	Where piping allowed, I was able to remove downspout and remount to the wall behind the downspout. Where piping needed to be modified to go behind the downspout, I mounted Kindorf to the wall to bring the conduit out around the downspouts while also being able to support it after reconnection where the pipe was pulled apart. In area where there was no downspout, I was able to loosen straps along the run and reconnect pipe due to slack in other connections.							
Diagnosis: Initial Work Order	along soffit Repair to conduit mounted, east side of bldg 1003.							
Diagnostic Fee	\$ 0							
Additional Labor Cost to Perform Repairs	<p>\$ 800</p> <p>SS \$100/hr x 8</p>							
Additional Cost	<p>\$ 165.04</p> <table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 33.33%;">Materials</td> <td style="width: 33.33%;">1</td> <td style="width: 33.33%;">165.04</td> <td style="width: 33.33%;">165.04</td> </tr> </table>				Materials	1	165.04	165.04
Materials	1	165.04	165.04					
Total Cost of Repair	\$ 965.04							