

## Additional Funding Request

<b>VA049</b>	<b>CSS# 27534 WO# 13164 Asset# NA</b>							
Description of Repairs	Labor and materials to replace 4 plastic thermostat covers in building 1003.							
Diagnosis: Initial Work Order	Repair clear plastic security boxes around thermostats, 4x, bldg 1003.							
Diagnostic Fee	<p>\$ 160</p> <p>Labor \$80/hr x 2</p>							
Additional Labor Cost to Perform Repairs	<p>\$ 160</p> <p>Labor \$80/hr x 2</p>							
Additional Material Cost to Perform Repairs	<p>\$ 192.80</p> <table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 40%;">Plastic thermostat covers</td> <td style="width: 10%; text-align: center;">4</td> <td style="width: 10%; text-align: center;">48.20</td> <td style="width: 10%; text-align: center;">192.80</td> </tr> </table>				Plastic thermostat covers	4	48.20	192.80
Plastic thermostat covers	4	48.20	192.80					
Total Cost of Repair	\$ 512.80							



# WORK ESTIMATE

CSS #:

28578

Work Order #:

13971

Emergency

Urgent

Routine

Company Name:	Tidewater, Inc.		Facility ID:	MD024
Contractor POC:	Adam Cology			
Telephone No:	740-819-6207		Building/Location; (e.g., Classroom/Room #)	
E-Mail Address:	<a href="mailto:adam.cology@tideh2o.net">adam.cology@tideh2o.net</a>			
Assigned Technician(s):	John Brown			

## DESCRIPTION of WORK and EXPLANATION for REPAIRS or REPLACEMENT

Labor and materials to replace 4 plastic thermostat covers in building 1003.

LABOR/MATERIAL		MATERIAL/ SUB UNIT DOLLAR AMOUNT	LBR/HR \$80	LINE ITEM TOTAL DOLLAR AMOUNT
ITEM	QUANTITY			
Diagnostic			2	\$160.00
Plastic Universal Thermostat Cover	4	\$48.20		\$192.80
Labor			2	\$160.00
<b>SUB-TOTAL COSTS:</b>		<b>Materials Total</b>	<b>\$192.80</b>	<b>Labor</b> \$320.00
			<b>TOTAL</b>	<b>\$512.80</b>

# My Products

Reference Information



GRAINGER APPROVED

Plastic Universal Thermostat Guard, Off-White

Item # 4E649

Qty

4

Total

**\$153.00**

Your Price **\$38.25** / each

Availability

Expected to arrive Fri. Apr 09.







