

Region: 5

Location: VA099

CSS #: 28858

Maximo Work Order No.: 13640

Asset #: NA

Date Issued: 2/3/21

Original Description: The CAC Card Computer hard drive has failed - Associated Asset ID number - - Description of equipment or system - CAC Card Computer

Repairs Needed:

Replace the Access Control Laptop, update server software, transfer licensing and flash galaxy boards to latest version at the Beford VA, USARC.

RS Means Line Buildup and Labor Summary (Data Version 2017, Q4):

Quantity	Line Item Number	Description	Labor Hours	Labor Rate/Hr	Materials	Equipment	Total
--	NA	Access Control Laptop	--	--	\$1,200.00	--	\$1,200.00
--	NA	LoCurrent Labor	16	\$75.00	--	--	\$1,200.00
--	NA	LoCurrent Administrative	1	\$100.00	--	--	\$100.00
--	NA	TWI Coordination	2	\$80.00	--	--	\$160.00

Estimate Summary:

Labor Hours	Labor Cost	Material Cost	Equipment	Total Cost	CE Factor	Total Estimate
19	\$1,460.00	\$1,200.00		\$2,660.00	100%	\$2,660.00

LoCurrent Systems, LLC
3522 County Highway 11
Cooperstown, NY 13326
(607)293-7300
locurrent@gmail.com



Estimate

ADDRESS

Tidewater Inc.
6625- A Selnick Drive
Elkridge, MD 21075

ESTIMATE # 1729

DATE 02/03/2021

P.O. NUMBER

Bedford, VA099 Replace Laptop

	ACTIVITY	QTY		AMOUNT
02/03/2021	Services Bedford, VA USARC VA099 Replace Access Control Laptop CSS#28858 WO#13640	1	2,500.00	2,500.00

Dear Ms. Lowery:

As per your request, LoCurrent Systems is pleased to provide a quotation to replace the Access Control Laptop, Update Server Software, Transfer Licensing and Flash Galaxy Boards to latest versions at the Bedford, VA USARC.

Cost Breakdown:

(1) new Access Control
Laptop.....\$1,200.00
(2) men 8 hours @
\$75.....\$1,200.00
Administrative.....\$100.00

Grand
Total.....\$2,500.00

The cost for the above mentioned work is \$2,500.00.

If acceptable, please do not hesitate to contact us.

Thank you for thinking of LoCurrent Systems.

Sincerely,

Antonietta LoRusso

TOTAL	\$2,500.00
-------	------------

Accepted By

Accepted Date

   		DELL Latitude E5570 19.5V 3.34A/4.52A Reg Model/型号: N48E 型号 Input/输入/輸入/Daya 19.5V 3.34A/4.52A www.dell.com Raheen Business Park Limerick, Ireland 中國製造/中国製造 DPIN: NY47M A00 CPC	
10019463374 SERVICE TAG(S/N): 4LPBVF2		MFG YR: 2017 EXPRESS SERVICE CODE	

10019463374
 SERVICE TAG(S/N): 4LPBVF2 MFG YR: 2017 EXPRESS SERVICE CODE

Windows Boot Manager

Windows has encountered a problem communicating with a device connected to your computer.

This error can be caused by unplugging a removable storage device such as an external USB drive while the device is in use, or by faulty hardware such as a hard drive or CD-ROM drive that is failing. Make sure any removable storage is properly connected and then restart your computer.

If you continue to receive this error message, contact the hardware manufacturer.

File: \Boot\BCD

Status: 0xc00000e9

Info: An unexpected I/O error has occurred.

ENTER=Continue

ESC=Exit