

Additional Funding Request

MD002	CSS# 29653 WO# 15391				
Description of Repairs	Tidewater proposes labor and materials to replace 4 emergency ballasts, replace 1 T-5 ballast, 1 regular T-8 ballast, and 8 tubes.				
Diagnosis: Initial Work Order	Repair T8 lights burnt out, 4x, rm 129, bldg. 001. Repair 2x T8 male latrine 2nd floor, and 12x T8 lobby 2nd floor, bldg. 001.				
Diagnostic Fee	\$ 160 Labor \$80/hr x 2				
Additional Labor Cost to Perform Repairs	\$ 640 Labor \$80/hr x 8				
Additional Material Cost to Perform Repairs	\$ 1,476.19 <table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 50%;">Materials (see attached detail)</td> <td style="width: 10%; text-align: center;">1</td> <td style="width: 10%; text-align: center;">1476.19</td> <td style="width: 10%; text-align: center;">1476.19</td> </tr> </table>	Materials (see attached detail)	1	1476.19	1476.19
Materials (see attached detail)	1	1476.19	1476.19		
Total Cost of Repair	\$ 2,276.19				



WORK ESTIMATE

CSS #:

Work Order #:

Emergency

Urgent

Routine

Company Name:	Tidewater, Inc.	Facility ID:	MD002
Contractor POC:	Adam Colopy		
Telephone No:	740-819-6207	Building/Location; (e.g., Classroom/Room #)	
E-Mail Address:	adam.colopy@tideh2o.net		
Assigned Technician(s):	John Brown		

DESCRIPTION of WORK and EXPLANATION for REPAIRS or REPLACEMENT

Labor and materials to replace 4 emergency ballasts, replace 1 T-5 ballast, 1 regular T-8 ballast, and 8 tubes.

LABOR/MATERIAL		MATERIAL/ SUB UNIT DOLLAR AMOUNT	LBR/HR \$80	LINE ITEM TOTAL DOLLAR AMOUNT
ITEM	QUANTITY			
Diagnostic			2	\$160.00
Materials (see attached detail)	1	\$1,476.19		\$1,476.19
Labor			8	\$640.00
SUB-TOTAL COSTS:		Materials Total	\$1,476.19	Labor \$800.00
			TOTAL	\$2,276.19

Cart

[Submit Order](#)

POWER SENTRY



Emergency FLUOR Ballast,
PowerSentry, 86W

Item # **460K01**



Qty
4

Your Price

\$258.48 / each

Total **\$1,033.92**



Add Extended Protection Plan
for **\$62.50** /each



[Plan Details and Exclusions](#)

Availability

Expected to arrive **Wed. Nov 17.**

[Remove](#)

ADVANCE



Centium(TM), Electronic,
Fluorescent Ballast, Ballast
Start Type Programmed

Item # **1FYF7**

Qty
1

Your Price

\$71.34 / each

[Add Extended Protection Plan](#)



Home



Cart



Account



Branches



More

Cart

[Submit Order](#)

Order Summary

Subtotal	\$1,105.26
Estimated Tax	\$66.32
Estimated Standard Shipping	FREE
Estimated Total	\$1,171.58

Availability, shipping, tax & promotions are not final until you complete your order.

 [Add Promotional Code](#)

Purchase Order Number

PO Number

Optional

My Products

Referenc...nformation 

POWER SENTRY

Emergency FLUOR Ballast,
PowerSentry, 86W

Item # **460K01**









1941
2101

PS1400
DESIGNER BATTERY PACK
UL Listed
Suitable for Use in

Eco-10™

ECO-T528-277-2

Programmed Rapid Start 10 % Electronic Fluorescent Dimming Ballast

LUTRON

Coopersburg, PA 18036 USA

277 V-

PRINTED BY
LUTRON

Use only with two 28 W T5 HE rapid start lamps.

277 V- 60 Hz 0.25 A Max.

Complies with FCC-Part 18. No PCB's.

Use only with wire and rapid start sockets rated for 600 V.

Use only within an electrical enclosure.

Ballast and fixture must be grounded.

To remove wire, press button on top of connector and pull wire.

Warranty void if unit is opened.