

Additional Funding Request

MD002	CSS# 30794 WO# 14354 Asset# NA							
Description of Repairs	Labor and materials to replace the mechanical lockset to interior door room 205.							
Diagnosis: Initial Work Order	Leverset change to lockset to match existing building type. Bldg 001, rm 205 interior.							
Diagnostic Fee	<p>\$ 160</p> <p>Labor \$80/hr x 2</p>							
Additional Labor Cost to Perform Repairs	<p>\$ 240</p> <p>Labor \$80/hr x 3</p>							
Additional Material Cost to Perform Repairs	<p>\$ 365.75</p> <table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 50%;">Mechanical Lockset</td> <td style="width: 10%; text-align: center;">1</td> <td style="width: 10%; text-align: center;">365.75</td> <td style="width: 10%; text-align: center;">365.75</td> </tr> </table>				Mechanical Lockset	1	365.75	365.75
Mechanical Lockset	1	365.75	365.75					
Total Cost of Repair	\$ 767.75							



WORK ESTIMATE

CSS #:

30794

Work Order #:

14354

Emergency

Urgent

Routine

Company Name:	Tidewater, Inc.		Facility ID:	MD002
Contractor POC:	Adam Cology			
Telephone No:	740-819-6207		Building/Location; (e.g., Classroom/Room #)	
E-Mail Address:	adam.cology@tideh2o.net			
Assigned Technician(s):	John Brown			

DESCRIPTION of WORK and EXPLANATION for REPAIRS or REPLACEMENT

Labor and materials to replace the mechanical lockset to interior door room 205.

LABOR/MATERIAL		MATERIAL/ SUB UNIT DOLLAR AMOUNT	LBR/HR \$80	LINE ITEM TOTAL DOLLAR AMOUNT
ITEM	QUANTITY			
Diagnostic			2	\$160.00
Mechanical Lockset	1	\$365.75		\$365.75
Labor			3	\$240.00
SUB-TOTAL COSTS:	Materials Total	\$367.75	Labor	\$400.00
			TOTAL	\$767.75

Cart

Submit Order

My Products



GRAINGER APPROVED

Mortise Lockset,
Mechanical, Extra Heavy
Duty, Different, Satin

Item # **35HU41**

Qty

1

Your Price

\$290.28 / each

Final Destination

! Please select a final destination

Availability

Expected to arrive Fri. May 28.

[Remove](#)

Delivery Method