

Additional Funding Request

NY127	CSS# 31537 WO# 14391							
Description of Repairs	Labor and materials to replace temperature control switch due to bad relay and set the temperature, and run for 2 hours to test operation.							
Diagnosis: Initial Work Order	Dining Facility Refrigerator will not cool.							
Diagnostic Fee	\$ 160 Labor \$80/hr x 2							
Additional Labor Cost to Perform Repairs	\$ 400 Labor \$80/hr x 5							
Additional Material Cost to Perform Repairs	\$ 452.43 <table border="1"><tr><td>Control XR02CX-4NFQ RED-8FT S</td><td>1</td><td>452.43</td><td>452.43</td></tr></table>				Control XR02CX-4NFQ RED-8FT S	1	452.43	452.43
Control XR02CX-4NFQ RED-8FT S	1	452.43	452.43					
Total Cost of Repair	\$ 1,012.43							



WORK ESTIMATE

CSS #: 31537

Work Order #: 14391

Emergency ☒

Urgent ☐

Routine ☐


Company Name:	Tidewater, Inc.	Facility ID:	NY127
Contractor POC:	Adam Colopy		
Telephone No:	740-819-6207	Building/Location; (e.g., Classroom/Room #)	
E-Mail Address:	adam.colopy@tideh2o.net		
Assigned Technician(s):	Patrick Brown		

DESCRIPTION of WORK and EXPLANATION for REPAIRS or REPLACEMENT

Labor and materials to replace temperature control switch due to bad relay and set the temperature, and run for 2 hours to test proper operation.

LABOR/MATERIAL		MATERIAL/ SUB UNIT DOLLAR AMOUNT	LBR/HR \$80	LINE ITEM TOTAL DOLLAR AMOUNT
ITEM	QUANTITY			
Diagnostic			2	\$160.00
Control XR02CX-4N4FQ RED-8FT S	1	\$452.43		\$452.43
Labor			5	\$400.00
SUB-TOTAL COSTS:		Materials Total	\$452.43	Labor \$560.00
TOTAL			\$1,012.43	







POWER
SWITCH



REFRIGERATOR

NY0127-01 Asset#190917-659