

Additional Funding Request

VA049	CSS# 31731 WO# 14672				
Description of Repairs	Moore's is proposing to replace two (2) failed damper actuator motors on air handler unit 1 that serves the second floor offices, as well as start, test, and ensure proper operation.				
Diagnosis: Initial Work Order	AC out on 2nd floor in command suite.				
Diagnostic Fee	\$ 360 Labor \$120/hr x 3				
Additional Labor Cost to Perform Repairs	\$ 480 Labor \$120/hr x 4				
Additional Material Cost to Perform Repairs	\$ 753.47 <table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 50%;">Materials (see attached detail)</td> <td style="width: 10%; text-align: center;">1</td> <td style="width: 10%; text-align: center;">753.47</td> <td style="width: 10%; text-align: center;">753.47</td> </tr> </table>	Materials (see attached detail)	1	753.47	753.47
Materials (see attached detail)	1	753.47	753.47		
Total Cost of Repair	\$ 1,593.47				



P.O. Box 119 • Altavista, VA 24517 • 24 Hour Service: 800.789.7199 • Fax: 888.722.2712 • MooresElectric.com

Proposal

July 21, 2021

Quotes are valid for 30 days.

USARC - VA049 6700 Strathmore Rd North Chesterfield VA 23237 PO: 14672 Email	Contact Name Telephone Cell Phone Fax Number	Mary Lowery & Adam Colopy 0.00 614-623-9569 0.00
---	---	---

DESCRIPTION OF EQUIPMENT:

Unit 1
Trane
Model # CGAM070A
Serial # U10C14744

DESCRIPTION OF PROBLEM:

Arrived on site, went through check in process at security. Gained access to 80th building. Spoke with site staff through doorbell camera and was let into site, once inside of building located staff on second floor and checked in. Gained access to second floor mechanical room, performed check of controls went over set points and actual space temperatures. Upon further investigation found the supply damper for the second-floor command center closed as the damper actuator motor has failed. Opened damper and monitored space temperature, second floor command suite is now cooling properly. Performed check of all air handler unit dampers and found damper actuator for zone 5 second floor to have failed as well. Performed check of chiller while onsite and found it to be operating properly at this time.

DESCRIPTION OF REPAIRS:

Moore's is proposing to replace two failed damper actuator motors on air handler unit 1 that serves the second floor offices. Will start, test, and ensure proper operations.

MATERIAL, EQUIP OR PARTS

Damper Actuator	Quantity	Sell price
	2.00	\$ 620.47
Freight	1.00	\$ 78.00
Truck Fee	1.00	\$ 55.00
	Material Total	\$ 753.47

LABOR ITEMIZED

Labor - Incurred	3	\$ 120.00	\$ 360.00
Labor - One Man	4	\$ 120.00	\$ 480.00
		Labor Total	\$ 840.00

Thank you for your business. If you have any questions or concerns, please feel free to contact us via telephone or quotes@mooreselectric.com

Materials	\$ 753.47
Labor	\$ 840.00

TOTAL **\$ 1,593.47**

Robert Lowery, Changeout Estimator 434-309-2591
Ian Harris, Estimator 434-309-2497
James Davis, Estimator 434-309-2568
Marvin Slaughter, Estimator 434-369-3514
Jared Underwood, Estimator 434-306-2446

Approved by: _____

Standard Terms and Conditions

Payments past 30 days are subject to 1.5% monthly service charge on unpaid balance. Additional charges for payments made through credit cards may apply. Late payments sent to collections or legal process the purchaser agrees to pay all costs, expenses, and reasonable attorney fees.

THANKS

CHUCK



M & M CONTROLS BR 42
 3102 W. CLAY STREET
 RICHMOND, VA 23230
 804-752-3423 Fax 804-752-4620

Quotation

Order Date	Order Number
07/21/2021	S1533372
ORDER TO:	
M & M CONTROLS BR 42	
3102 W. CLAY STREET	
RICHMOND, VA 23230	
Phone: 804-752-3423	

QUOTE TO: SHIP TO:
 MOORE'S ELECTRICAL & MECHANICAL MOORE'S ELECTRICAL & MECHANICAL
 P O BOX 119 101 EDGEWOOD AVENUE
 ALTAVISTA, VA 24517 ALTAVISTA, VA 24517

Customer Number	Customer Order Number	Release Number	Salesperson	
9034	JOSH/MS7520		Tim Johnson	
Writer	Ship Via	Terms	Expr Date	Freight Allowed
CHARLES ATWELL	WC WILL CALL	NET 30 DAYS	09/04/2021	No
Description		Order Qty	Net Prc	Ext Prc
MS7520A2007 DAMPER ACTUATOR MODULATING SPRING RETURN 175 IN/LB 0-10VDC, 4-20MA, FLOATING, 0/2-10 VDC FEEDBACK.		2ea	258.530	517.06
			Subtotal	517.06
			Tax	*****
			Freight	0.00
			Handling	0.00
			Total	517.06

This email and any files transmitted with it are confidential and intended solely for the use of the individual or entity to whom they are addressed. If you have received this email in error, please notify the sender immediately and delete this email from your system. You may not disclose, copy or distribute the contents of this email as it is strictly prohibited.



Main

Reports



Chiller Mode: Running

Circuit 1 Mode: Running

Circuit 2 Mode: Running

Active Chilled Water Setpoint: 42.5 F

Active Demand Limit Setpoint:

Outdoor Air Temperature:

ADAPTIVE CONTROL™



START
DEC. OFFICE
COMMAND
CENTER

SEC.
COM
Cen

Envision for BACtalk - ACES/80TH

BACtalk Edit View Tools Help

Wednesday, 7/21/2021 9:59:22AM

Previous

Zone Dampers AHU-1


	Space Temp	Heat SP	Cool SP	ACT SP	Damper %	SF Status
Zone 1-1	66.9	70.0	72.0	70.0	0.0	Active
Zone 1-2	71.2	70.0	72.0	72.0	0.0	Active
Zone 1-3	72.9	68.0	75.0	72.0	100.0	Active
Zone 1-4	71.9	70.0	72.0	72.0	40.4	Active
Zone 1-5	68.5	69.0	72.0	72.0	0.0	Active

Zone Dampers AHU-2

	Space Temp	Heat SP	Cool SP	ACT SP	Damper %	SF Status
Zone 2-1	72.5	70.0	72.0	72.0	100.0	Active
Zone 2-2	73.1	70.0	72.0	72.0	100.0	Active
Zone 2-3	72.4	70.0	72.0	72.0	100.0	Active
Zone 2-4	73.6	70.0	72.0	72.0	100.0	Active
Zone 2-5	74.7	70.0	72.0	73.0	100.0	Active
Zone 2-6	72.6	70.0	72.0	72.0	78.7	Active



Nero
StartSmart



Spybot -
Search...



Windows
Media Player