

Additional Funding Request

MD024	CSS# 32132 WO# 14839							
Description of Repairs	LoCurrent proposes labor and materials to replace Loop Detector Modules on Gate 1 and Gate 2. LoCurrent already performed temporary repairs when investigating.							
Diagnosis: Initial Work Order	Gate 1 is not working properly and loop on gate 2 is not working properly.							
Diagnostic Fee	\$ 450 Labor cost incurred \$450							
Additional Labor Cost to Perform Repairs	\$ 600 Labor \$75/hr x 8							
Additional Material Cost to Perform Repairs	\$ 500.00 <table border="1"><tr><td>Loop Detector Modules</td><td>2</td><td>250.00</td><td>500.00</td></tr></table>				Loop Detector Modules	2	250.00	500.00
Loop Detector Modules	2	250.00	500.00					
Total Cost of Repair	\$ 1,550.00							

LoCurrent Systems, LLC
3522 County Highway 11
Cooperstown, NY 13326
(607)293-7300
locurrent@gmail.com



Estimate

ADDRESS

Tidewater Inc.
6625- A Selnick Drive
Elkridge, MD 21075

ESTIMATE # 1843
DATE 08/20/2021

ACTIVITY		QTY		AMOUNT
08/20/2021	Services CSS#32132 WO#14839 Curtis Bay Baltimore, MD USARC MD024 Replace Gate 1 and Gate 2 Loop Detector Modules	1	1,100.00	1,100.00
Dear Ms. Mascelli:				
As per your request, LoCurrent Systems is pleased to provide a quotation to replace Loop Detector Modules at the Curtis Bay, USARC MD024.				
Cost Breakdown:				
(2) Loop Detector Modules.....\$500.00				
(1) man, 8 hrs. @ \$75.....\$600.00				
Grand Total.....\$1,100.00				
Sincerely,				
Antonietta LoRusso				
TOTAL				\$1,100.00

Accepted By

Accepted Date

LoCurrent Systems, LLC
3522 County Highway 11
Cooperstown, NY 13326
(607)293-7300
locurrent@gmail.com



INVOICE

BILL TO

Tidewater Inc.
6625- A Selnick Drive
Elkridge, MD 21075

INVOICE # 1988
DATE 08/20/2021
DUE DATE 09/19/2021
TERMS Net 30

P.O. NUMBER

Curtis Bay MD024 Diagnose Gates

ACTIVITY	QTY	RATE	AMOUNT
Services As per Estimate #1842: CSS#32132 WO#14839 Curtis Bay Baltimore, MD USARC MD024 Diagnose Gate 1 and 2	1	450.00	450.00

Completed temporary fix of both Gates.
Found that Loop Detector Module needed to be replaced in both Gate Operators.
Will send Follow Up Quotation.

Dear Ms. Mascelli:

As per your request, LoCurrent Systems is pleased to provide a quotation to diagnose the issues being experienced with "Gate 1" and "Gate 2" as per SOW "gate 1 is not working properly and loop on gate 2 is not working properly".

Cost to diagnose is \$450.00.


Sincerely,


Antonietta LoRusso

If you have any questions regarding this invoice, please contact Antonietta LoRusso at (607)293-7300.

BALANCE DUE

\$450.00





460V 3Ø

SEE THE T-TOUCH MANUAL FOR
MORE INFORMATION
ON THE T-TOUCH SYSTEM

© 2000 Hydrex







