



Proposal

CMI Management
Mr. Joe Bayne
5285 Shawnee Rd.
Alexandria, VA. 22312

April 13, 2022

RE:W/O 16882 CSS#32211 NY001

Sump pump

- Service call
- Test pumps and evaluate
- Pump #1 has failed bearing and rotted output pipe
- Pump#2 is seized in pump section.

Remove (2) pedestall style pump assemblies and replace with
Cast iron submersible pumps.
Re-plumb sump pit outlet piping to accept submersible pumps
Connect pumps to existing control panel.

2 Zollener 2vj65 cast iron pumps (Grainger).	2031.10	4062.22
10ft 1-1/2 Galvanized pipe. USA (Grainger)	504.80.	504.80
5ft 1-1/2 Galvanized Pipe USA (Grainger).	252.24.	252.40
Misc Fittings & Sealant.		75.00

		4894.42
12hrs @ 120.00.		1440.00

sub-total.		6334.42
20%profit/OH		1266.88

Total.		7601.30

701 Randall Rd Ballston Spa, NY 12020 TEL 518-441-6003 FAX 518-399-5440

Email rdpostulka@verizon.net

INDUSTRIAL

COMMERCIAL

INSTITUTIONAL