

## Additional Funding Request

MD019	CSS# 33201 WO# 15388							
Description of Repairs	S&S proposes to remove and replace the flame switch on boiler #1, and then complete a system check to ensure everything is running properly.							
Diagnosis: Initial Work Order	#1 Boiler would not lite off.							
Diagnostic Fee	\$ 350  Labor cost incurred \$350							
Additional Labor Cost to Perform Repairs	\$ 400  Labor \$100/hr x 4							
Additional Material Cost to Perform Repairs	\$ 87.60 <table border="1"><tr><td>Flame Switch #2-30-001334</td><td>1</td><td>87.60</td><td>87.60</td></tr></table>				Flame Switch #2-30-001334	1	87.60	87.60
Flame Switch #2-30-001334	1	87.60	87.60					
Total Cost of Repair	\$ 837.60							



# S&S MECHANICAL

**S&S Mechanical**  
4831 South Crain Highway  
Upper Marlboro, MD 20772

Tel. 1 - (301) 574-1555  
Fax. 1 - (301) 574-1558  
www.sandsmidatlantic.com

## CUSTOMER QUOTATION NO. 779

Tidewater, Inc.  
Tidewater, Inc  
6625 Selnick Dr.  
Suite A  
Elkridge MD 21075

**Quote Name:** 15388  
**Quote No:** 779  
**Site:** MD019 Greenspring Avenue  
**Site Contact:**  
**Salesperson:** Lindsay Ruby  
**Created Date:** 10/28/2021  
**Valid For:** 30 Day(s)

**WO#: 15388**

**CSS Ticket Number: 33201**

**Problem:** #1 Boiler would not lite off.

S&S proposes to remove & replace the flame switch on Boiler #1.  
S&S will then complete a system check to ensure everything is running properly.

### Service

Item	Quantity	Unit Price	Total
Flame Switch #2-30-001334	1.00	\$87.60	\$87.60
Diagnosis Fee	1	\$350.00	\$350.00
HVAC Labor Rate	4	\$100.00	\$400.00
<b>Sub-Total ex Tax</b>			\$837.60
<b>Tax</b>			\$0.00
<b>Total inc Tax</b>			\$837.60

<b>Labor</b>	\$750.00
<b>Materials</b>	\$87.60
<b>Sub-Total ex Tax</b>	\$837.60
<b>Tax</b>	\$0.00
<b>Total inc Tax</b>	\$837.60

SUBTOTAL	\$146.00
TAX (6.0%)	\$8.76
TOTAL	\$154.76

2-30-0013

 **Fulton**

MAX SERVICE  
RATINGS

\* 75" W.C.

\* 190° F.

AIR PRESSURE  
ONLY.

Adjustable Range and Mounting

DIAPHRAGM  
(MEMBRANE)

VERTICAL

.17" TO 5.0" W.C.

DIAPHRAGM  
HORIZONTAL  
1.0" TO 5.0" W.C.  
MOUNTING  
INSTRUCTIONS