

Additional Funding Request

NY067	CSS# 34467 WO# 16636 Asset# NA
Description of Repairs	Labor and materials to remove the flush valve and mounting bolts then remove the broken toilet , we will clean up the old flange and install a new wax seal , we will then install a new toilet and rebuild the existing flush valve and test to ensure it is working properly
Diagnosis: Initial Work Order	Repair toilet in room 151. Valve leaks when flushed.
Diagnostic Fee	\$ 160 TW Labor \$80/hr x 2
Additional Labor Cost to Perform Repairs	\$ 680 LC Labor \$85/hr x 8
Additional Material Cost to Perform Repairs	\$ 262.40 See attached detail
Total Cost of Repair	\$ 1102.40

To:

TIDEWATER INC
6625 SELNICK DR #A
ELKRIDGE MD 21075-6220

Information

Date 03/14/2022
Customer Account Number 885295220
Grainger Quote Number 46531650
Customer Job Number
Contract Number
Grainger Representative John R Romano
Phone Number
Fax Number
Email
Grainger Tax ID 36-1150280

Item	Description Manufacturer Name & Model	Cat. Pg. #	Qty	\$ Quote	Ext. Price	Start Date	Exp. Date
15W677	Toilet Bowl,Elongated,Floor,Flush Valve AMERICAN STANDARD 2234001PL.020 Country of Origin: Mexico		1	131.61	131.61	03/14/2022	07/31/2022
22UR76	Wax Ring,Sloan, Zurn, American Standard GRAINGER APPROVED 22UR76 Country of Origin: China		1	3.40	3.40	03/14/2022	07/31/2022
2XJ94	Diaphragm Assembly,Manual>Toilets,1.6G PF SLOAN A1101A Country of Origin: USA		1	47.58	47.58	03/14/2022	07/31/2022
4TMH8	Toilet Seat,Elongated Bowl,Open Front AMERICAN STANDARD 5901100.020 Country of Origin: China		1	22.50	22.50	03/14/2022	07/31/2022
				Total \$ 205.09			

All orders are subject to the terms and conditions in your current contract with Grainger or to Grainger's current Terms of Sale as set forth on Grainger.com

Thank You!

Visit us at grainger.com



