

Additional Funding Request

VA099	CSS# 34513 WO# 16436				
Description of Repairs	Labor and materials to replace 3 faulty faulty flow sensors on VAV's that were discovered while diagnosing the building automation system. Two of the VAV's are in auditorium with high ceiling.				
Diagnosis: Initial Work Order	the facility is extremely hot inside				
Diagnostic Fee	\$ 640 Labor \$80/hr x 8				
Additional Labor Cost to Perform Repairs	\$ 480 Labor \$80/hr x 6				
Additional Material Cost to Perform Repairs	\$ 205.14 <table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 40%;">Low Pressure Sensor</td> <td style="width: 10%;">3</td> <td style="width: 10%;">68.38</td> <td style="width: 10%;">205.14</td> </tr> </table>	Low Pressure Sensor	3	68.38	205.14
Low Pressure Sensor	3	68.38	205.14		
Total Cost of Repair	\$ 1325.14				



WORK ESTIMATE

CSS #: 34513

Work Order #: 16436

Emergency

Urgent

X

Routine

Company Name:	Tidewater, Inc.		Facility ID:	VA099	
Contractor POC:	Adam Cology				
Telephone No:	740-819-6207		Building/Location; (e.g., Classroom/Room #)		
E-Mail Address:	adam.cology@tideh2o.net				
Assigned Technician(s):	Will Schultz				

DESCRIPTION of WORK and EXPLANATION for REPAIRS or REPLACEMENT

Labor and materials to replace 3 faulty faulty flow sensors on VAV's that were discovered while diagnosing the building automation system. Two of the VAV's are in auditorium with high ceiling.

LABOR/MATERIAL		MATERIAL/ SUB UNIT DOLLAR AMOUNT	LBR/HR \$80	LINE ITEM TOTAL DOLLAR AMOUNT
ITEM	QUANTITY			
Diagnostic			8	\$640.00
Low Pressure Sensor	3	\$68.38		\$205.14
Labor			6	\$480.00
SUB-TOTAL COSTS:		Materials Total	\$205.14	Labor \$1,120.00
			TOTAL	\$1,325.14

All discrepancies, repairs and deficiencies associated with this work order were completed according to the Description of Work Explanation for

Trane U.S. Inc.
RICHMOND PARTS SUPPLY
10404 LAKERIDGE PKWY STE 300
ASHLAND, VA 23005
USA
PH: 804-747-4774
Ashland@tranesupply.com

Order Number	
16970754	
Order Date	Page
3/11/2022 11:14:29	1 of 1

Quote Expires On 4/10/2022

Prepared For:

TIDEWATER INC
6625 SELNICK DR SUITE A
ELKRIDGE, MD 21075
USA

4105408700

Ship To:

TIDEWATER INC
10404 LAKERIDGE PKWY STE 300
ASHLAND, VA 23005
USA

Requested By: Will Schultz,

P21 ID: 1035611

Internal Account: 3880885

Payment Terms: N30

Customer No: 237607

National Account ID:

<i>PO Number</i>	<i>Ship Route</i>	<i>Quoted By:</i>
		Dionne Fraser

Unit Info: Make / Model / Serial

r12k95649

<i>Quantities</i>					<i>Item ID</i>	<i>Pricing UOM</i>	<i>Unit Price</i>	<i>Extended Price</i>
<i>Ordered</i>	<i>Allocated</i>	<i>Remaining</i>	<i>UOM Unit Size</i>	<i>Disp. Weight</i>	<i>Item Description</i>	<i>Unit Size</i>	<i>Store Pickup</i>	<i>HazMat</i>

Pickup Location-RICHMOND PARTS SUPPLY, 10404 LAKERIDGE PKWY STE 300, , ASHLAND, VA, 23005

3	0	3 EA	SEN02670	EA	52.03	156.09
---	---	------	----------	----	-------	--------

Non-Returnable	1.0	0.50 SENSOR; PRESSURE; LOW DIFFERENTIAL; 5VDC ; PRESSURE INPUT: 0 - 5 INCH W.C., W/CONNECTOR	1.0	Y	N
----------------------	-----	---	-----	---	---

Total Lines: 1

SUB-TOTAL 156.09

CENTRAL VIRGINIA DISTRICT TAX 1.09

VIRGINIA TAX 6.72

HANOVER TAX 1.56

QUOTE TOTAL 165.46

U.S. Dollars

This is a quote, not an invoice. Prices quoted are valid for 30 days from the date issued unless otherwise indicated, with the exceptions of commodity and equipment pricing - which are subject to change without notice. Tax is an estimate and is subject to changes in shipping address and applicable tax rates. Shipping and Handling charges will be applied if necessary at the time of the order. Quoted items are subject to availability and are not guaranteed to be in stock. Returned parts may be subject to restocking fees and Special Order parts may not be returnable.

All purchases are subject to Trane Parts and Supplies terms of sale, www.trane.com/PartsTermsOfSale