

Additional Funding Request

NY051	CSS# 34780 WO# 16899 Asset# NA
Description of Repairs	Labor and materials replace Belimo Valve
Diagnosis: Initial Work Order	Repair drip / leak from piping in mechanical room, center of the ceiling.
Diagnostic Fee	\$ 200
Additional Labor Cost to Perform Repairs	\$ 392 HydeStone Labor (see attached)
Additional Material Cost to Perform Repairs	\$ 318.06 Belimo Valve
Total Cost of Repair	\$ 910.06

Hyde-Stone Mechanical Contractors,

Inc. 22962 Murrock Circle
Watertown, NY 13601
Fax

To: TIDE WATER, INC
6625 SELNICK DRIVE, SUITE A

Attn: ELKRIDGE, MD 21075
PATRICK BROWN - TW

Work Address: US ARMY RESERVE - TIDEWATER
60 EAST 9TH STREET
OSWEGO NY
13126

QUOTATION

Quote #: 0000001645-000
Quote Type: Work Order
Reference: 14040/DEREK/16899
Cross Ref:
Work Order: n/a
Customer: USARMYOSWE
Terr/sale: HSE
Current Date: Apr 15, 2022
Expiry Date: N/A

FOR USE WITH
WATER ONLY
MAX. TEMPERATURE
200°F (93°C)
MAX. PRESSURE
200 PSI (1380 KPa)

200
H
C

GRISWOLD CONTROLS
Model
1000-1000-1000