



## Additional Funding Request

<b>NY051</b>	<b>CSS #35243 WO# 16862 Asset# NA</b>							
Description of Repairs	Labor and materials to replace damaged ceiling tiles throughout the building.							
Diagnosis: Initial Work Order	Repair ceiling tiles. Multiple wet tiles throughout center.							
Diagnostic Fee	\$ 160 TWI \$80/ hr x 2							
Additional Labor Cost to Perform Repairs	\$ 560 TWI \$80/hr x 7							
Additional Cost	<p>\$ 180.50</p> <table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 40%;">Materials (See attached detail)</td> <td style="width: 15%;">2</td> <td style="width: 15%;">90.25</td> <td style="width: 15%;">180.50</td> </tr> </table>				Materials (See attached detail)	2	90.25	180.50
Materials (See attached detail)	2	90.25	180.50					
Total Cost of Repair	\$900.50							







Item	In Store	Qty	Item Total
Armstrong CEILINGS Textured 2 ft. x 2 ft. Lay-in Ceiling Tile (64 sq. ft. / Case) Model #949 Store SKU #1005411659	 Aisle Bay	2	\$141.02
Subtotal			\$141.02
Shipping			\$0
Sales Tax			\$0
<b>Est. Total</b>			<b>\$141.02</b>