

Additional Funding Request

NY051	CSS # 35266 WO# 16863 Asset# NA
Description of Repairs	Labor and materials to remove three of the step flashing, redo the sealant, and reinstall. Will then redo the sealant on several other pieces of step flashing.
Diagnosis: Initial Work Order	Repair roof leak above room 107.
Diagnostic Fee	\$ 160 TWI \$80/ x 2
Additional Labor Cost to Perform Repairs	\$ 480 TWI \$80/ x 6
Additional Cost	\$ 135.42 Clear All-Purpose Patch (1)- \$135.42
Total Cost of Repair	\$ 775.42





Item	In Store	Qty	Item Total
 Henry 10.1 oz. 212 Clear All-Purpose Patch Model #HE212202 Store SKU #111703	 Aisle 20 Bay 011	10	\$105.80
<hr/>			
Subtotal			\$105.80
Shipping			\$0
Sales Tax			\$0
Est. Total			\$105.80
View Cart			