

Additional Funding Request

NY067	CSS# 35327 WO# 16872				
Description of Repairs	Labor and materials to replace several ceiling tiles throughout the building with new.				
Diagnosis: Initial Work Order	Repair ceiling tiles, multiple wet tiles in main hallways and offices.				
Diagnostic Fee	\$ 160 Labor \$80/hr x 2				
Additional Labor Cost to Perform Repairs	\$ 480 Labor \$80/hr x 6				
Additional Material Cost to Perform Repairs	\$ 180.51 <table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 40%;">Materials (See attached detail)</td> <td style="width: 10%; text-align: center;">1</td> <td style="width: 15%; text-align: center;">180.51</td> <td style="width: 15%; text-align: center;">180.51</td> </tr> </table>	Materials (See attached detail)	1	180.51	180.51
Materials (See attached detail)	1	180.51	180.51		
Total Cost of Repair	\$ 820.51				



Item	In Store	Qty	Item Total
Armstrong CEILINGS Textured 2 ft. x 2 ft. Lay-in Ceiling Tile (64 sq. ft. / Case) Model #949 Store SKU #1005411659	 Aisle Bay	2	\$141.02
Subtotal			\$141.02
Shipping			\$0
Sales Tax			\$0
Est. Total			\$141.02