

Additional Funding Request

Submitted: **06/06/22**

VA049	CSS 623 WO 17775			
Description of Repairs	Labor and Materials to Will disconnect power to motor. Remove pulley from old motor and install on new motor. Remove old motor from mount on exhaust fan and install new motor. Put on new belt and wire up motor.			
Original SC Investigative Diagnosis	\$160			
Diagnosis: Initial Work Order	Motor needs to be replaced on exhaust fan on main roof.			
Explanation of Additional Costs for Repairs	N/A			
Additional Material Cost to Perform Repairs	Materials: \$ 274.30			
	ITEM	QUANTITY	UNIT PRICE	TOTAL
	Materials (See attached for details)	1	274.30	274.30
Additional Labor Cost to Perform Repairs	Labor: \$320 4 hours each/ \$80			
Total Cost of Repair	\$754.30			



WORK ESTIMATE

CSS #: 623

Work Order #: 17775

Emergency

Urgent

Routine

X

Company Name:	Tidewater, Inc.	Facility ID:	VA049	
Contractor POC:	Adam Colopy			
Telephone No:	740-819-6207	Building/Location; (e.g., Classroom/Room #)		
E-Mail Address:	adam.colopy@tideh2o.net			
Assigned Technician(s):	Will Schultz			
DESCRIPTION of WORK and EXPLANATION for REPAIRS or REPLACEMENT				
Main roof Exhaust Fan unit/completed assembly needs replaced				
LABOR/MATERIAL				
ITEM	QUANTITY	MATERIAL/SUB UNIT DOLLAR AMOUNT	LBR/HR \$100	LINE ITEM TOTAL DOLLAR AMOUNT
Labor			4	\$320.00
Materials Cost	1	\$274.30		\$274.30
				\$0.00
Diagnostic Labor			2	\$160.00
SUB-TOTAL COSTS:		Materials Total	\$274.30	Labor \$480.00
TOTAL			\$754.30	



MAIN OFFICE: 11401 ROOSEVELT BLVD. PHILA., PA 19154-2102 PHONE: (215) 698-9100 EMAIL: info@uri.com