

Additional Funding Request

NY067	CSS# 89651 WO# 19224				
Description of Repairs	Labor and material to swap out a lock set onto the SIPR safe from another safe.				
Diagnosis: Initial Work Order	Repair SIPR Safe Locking Mechanism				
Diagnostic Fee	\$160.00				
Additional Labor Cost to Perform Repairs					
Additional Material Cost to Perform Repairs	<p>\$ 535.68</p> <table border="1" style="margin-left: auto; margin-right: auto;"> <tr> <td>Materials (See attached detail)</td> <td>1</td> <td>535.68</td> <td>535.68</td> </tr> </table>	Materials (See attached detail)	1	535.68	535.68
Materials (See attached detail)	1	535.68	535.68		
Total Cost of Repair	\$ 695.68				

Tick Tock Safe and Lock

PO Box 311

Liverpool, NY 13088

(315) 944-0532

service@ticktocksafeandlock.com

http://www.ticktocksafeandlock.com

**TICK TOCK**
SAFE AND LOCK

Estimate

ADDRESS

Tidewater Inc.
3761 Attucks Dr
Powell, OH 43065

ESTIMATE # 220918-01**DATE** 09/22/2022**EXPIRATION DATE** 09/22/2022**WORK ORDER/PO NUMBER**

Utica

DATE	DESCRIPTION	QTY	RATE	AMOUNT
	X09 Dial	1	26.00	26.00T
	X09 Spindle	1	57.00	57.00T
	X09/X10 Hub	1	20.00	20.00T
	X09/X10 Tube Kit	1	83.00	83.00T
	Install X10/2740 Lock	1	150.00	150.00T
	Travel	2	80.00	160.00T
				SUBTOTAL 496.00
				TAX 39.68
				TOTAL \$535.68

Accepted By

Accepted Date

