

CASTO TECHNICAL SERVICES, INC.

## SERVICE REPORT

DATE 06/28/2023 ARRIVAL TIME 9:00 DEPARTURE TIME 11:00 JOB/TCK. NO. 197843

DEPARTURE TIME 11:00 JOB/TCK. NO. 197843

JOB/TCK. NO. 197843

CUSTOMER P.O. NO. CSS# 89752 w/o 13373

**JOB NAME/LOCATION** USARC - Beaver WV002

**SERVICE REQUESTED** *Burnham segmented boiler is running correctly, but possible carbon monoxide has been detected by an HVAC*

Manufacture:			
Model#:			
Serial#:			
Refrigerant Added:	Qty	lb	oz
Refrigerant Removed:	Qty	lb	oz

- Leak Tested
- Leak Found
- Leak Repaired

Method: \_\_\_\_\_

Total Charge: \_\_\_\_\_

**WORK PERFORMED/UNIT INFO.**

Stopped by UPS to print off the COW form. Got on site and checked in with customer. Went to the boiler room and found the boiler out on ignition failure. Reset the alarm and watched it run. Pilot flame signal barely broke 1.5V, and main burner was failing to ignite. It really just looks like the boiler needs tuned. I called Reg and talked to him, he said the site manager was requesting that the boiler be cleaned, so I'll send a quote in to remove the burner and clean the inside of the boiler, then tune it. I packed up tools after that, did paperwork, and then left.

**NATURE OF WORK**

Regular Service \_\_\_\_\_

Quoted Service \_\_\_\_\_

Start-up/Warranty \_\_\_\_\_

SPD \_\_\_\_\_

Contract Service \_\_\_\_\_

Energy Management \_\_\_\_\_

**PARTS, MATERIALS AND SUBCONTRACTED SERVICES**

## **SUMMARY OF TIME**

JOB COMPLETE YES  NO  EXPLAIN \_\_\_\_\_

**SIGNATURE** \_\_\_\_\_

### **Customer Representative**