

## Additional Funding Request

<b>NY067</b>	<b>CSS# 90129 WO# 19382</b>				
Description of Repairs	Labor and material to access the ceiling to investigate the leak.				
Diagnosis: Initial Work Order	Repair ceiling tiles and investigate roof/plumbing/mechanical lines above for leaks.				
Diagnostic Fee					
Additional Labor Cost to Perform Repairs	<p>\$320.00</p> <p>TWI Labor \$80 x 4</p>				
Additional Material Cost to Perform Repairs	<p>\$ 288.00</p> <table border="1" style="margin-left: auto; margin-right: auto;"> <tr> <td>Materials (See attached detail)</td> <td>1</td> <td>288.00</td> <td>288.00</td> </tr> </table>	Materials (See attached detail)	1	288.00	288.00
Materials (See attached detail)	1	288.00	288.00		
Total Cost of Repair	\$ 608.00				





ASUS Dashcam