

Additional Funding Request

NY051	CSS# 90326 WO# 19732							
Description of Repairs	Repair main entrance door, key core is not working and will need to be repaired/replaced.							
Diagnosis: Initial Work Order	Labor and material to replace the SFIC keyed cylinder							
Diagnostic Fee	TWI Diagnostic Fee \$80 x 2 \$160.00							
Additional Labor Cost to Perform Repairs	Labor - \$172.50 Travel - \$240.00							
Additional Material Cost to Perform Repairs	\$ 25.00 <table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 40%;">Materials (See attached detail)</td> <td style="width: 10%; text-align: center;">1</td> <td style="width: 10%; text-align: center;">25.00</td> <td style="width: 10%; text-align: center;">25.00</td> </tr> </table>				Materials (See attached detail)	1	25.00	25.00
Materials (See attached detail)	1	25.00	25.00					
Total Cost of Repair	\$ 597.50							

Tick Tock Safe and Lock

PO Box 311
Liverpool, NY 13088
(315) 944-0532
service@ticktocksafeandlock.com
http://www.ticktocksafeandlock.com

**TICK TOCK**
SAFE AND LOCK

Estimate

ADDRESS

Tidewater Inc.
3761 Attucks Dr
Powell, OH 43065

ESTIMATE # 221024-01**DATE** 10/24/2022**EXPIRATION DATE** 11/24/2022**WORK ORDER/PO NUMBER**

Oswego

DATE	DESCRIPTION	QTY	RATE	AMOUNT
10/21/2022	Travel	1.50	80.00	120.00T
10/21/2022	Service Call	1	45.00	45.00T
10/21/2022	Labor	0.50	85.00	42.50T
	Travel	1.50	80.00	120.00T
	Labor	1	85.00	85.00T
	SFIC keyed cylinder	1	25.00	25.00T
				SUBTOTAL 437.50
				TAX 35.00
				TOTAL \$472.50

Accepted By

Accepted Date