

Additional Funding Request

NY051	CSS# 90326 WO# 19732						
Description of Repairs	Repair main entrance door, key core is not working and will need to be repaired/replaced.						
Diagnosis: Initial Work Order	Labor and material to replace the SFIC keyed cylinder						
Additional Labor Cost to Perform Repairs	Labor - \$172.50 Travel - \$240.00						
Additional Material Cost to Perform Repairs	\$ 25.00 <table border="1" style="width: 100%; border-collapse: collapse; margin-top: 5px;"> <tr> <td style="width: 55%;">Materials (See attached detail)</td> <td style="width: 10%; text-align: center;">1</td> <td style="width: 20%; text-align: right;">25.00</td> <td style="width: 15%; text-align: right;">25.00</td> </tr> </table>			Materials (See attached detail)	1	25.00	25.00
Materials (See attached detail)	1	25.00	25.00				
Total Cost of Repair	\$ 437.50						

Tick Tock Safe and Lock

PO Box 311

Liverpool, NY 13088

(315) 944-0532

service@ticktocksafeandlock.com

<http://www.ticktocksafeandlock.com>

Estimate

ADDRESS

Tidewater Inc.

3761 Attucks Dr

Powell, OH 43065

ESTIMATE # 221024-01**DATE** 10/24/2022**EXPIRATION DATE** 11/24/2022**WORK ORDER/PO NUMBER**

Oswego

DATE	DESCRIPTION	QTY	RATE	AMOUNT
10/21/2022	Travel	1.50	80.00	120.00T
10/21/2022	Service Call	1	45.00	45.00T
10/21/2022	Labor	0.50	85.00	42.50T
	Travel	1.50	80.00	120.00T
	Labor	1	85.00	85.00T
	SFIC keyed cylinder	1	25.00	25.00T

SUBTOTAL 437.50

TAX 35.00

TOTAL **\$472.50**

Accepted By

Accepted Date