

Facility Repair Proposal

Region: 4AZ1
Fac ID: PA027
Date: 11/9/2022

CSS # 90707
Maximo Work Order No.: 11310

Asset ID: XXXX

Original Work Request:
AAON RTU is not working properly.

Description of Repairs Needed:
Following investigate it has been determined that the heat exchanger and actuator requires replacement. Labor and materials to replace the heat exchanger and actuator on the AAON RTU.

Parts List:

- Heat Exchanger (K03008)
- Actuator (R14090)

Equipment List:

- Crane Rental

PM History:
NA

Cost Proposal:
See attached RS Means Estimate.

Total Cost: \$12,254.92

