

Additional Funding Request

NY067	CSS# 91555 WO# 20628				
Description of Repairs	Labor and material to a.) remove the relay board that is bad and install a new board. NOTE: we may need an additional ticket once the board is replaced				
Diagnosis: Initial Work Order	No Heat - Boiler #1				
Diagnostic Fee	NA				
Additional Labor Cost to Perform Repairs	$8 \times \$130.00 = \1040.000				
Additional Material Cost to Perform Repairs	<p>\$ 297.35</p> <table border="1" style="margin-left: auto; margin-right: auto;"> <tr> <td>Materials (See attached detail)</td> <td>1</td> <td>297.35</td> <td>297.35</td> </tr> </table>	Materials (See attached detail)	1	297.35	297.35
Materials (See attached detail)	1	297.35	297.35		
Total Cost of Repair	\$ 1337.35				



F.W. WEBB COMPANY

415 BROAD STREET
UTICA, NY 13501-1284
Phone: 315-724-3191 Fax: 315-292-6280

This is your **Quotation** from F.W. Webb Company.
Please review the products listed on this quotation for accuracy and completeness.

Quotation number: 79198130	Ship to: Tidewater, Inc. 6625 Selnick Drive Elkridge, MD 21075 410-540-8700	Bill to: Tidewater, Inc. 6625 Selnick Drive Elkridge, Md 21075 410-540-8700	
Quote Date : 01/10/2023			
Cust.Nbr: 198314	Customer PO: 5416304	Rel: Job: Quoted By: SEANM	Requested: 01/10/2023

Quantity	Description	Net Price	Total
1	HTP HTP7250P-580 Brd 199/399vwh And 850/modcon Dbl Stkg	\$297.350	\$297.35
		Subtotal	\$297.35
		Shipping	\$20.00
		Handling	\$0.00
		Tax	\$17.84
		Total	\$335.19

Thank you for the opportunity to provide product pricing to meet your business needs.

Please visit our website for additional products or information <http://www.fwwebb.com>

This Quotation is valid for 15 days after the above Quote Date.

* Restocking fees may apply on any Special Order Items.

Please Note: This email was sent from a notification-only address that cannot accept incoming email. Please do not reply to this message.

Maintenance
Record



3/29/18

DUNGS®