

Additional Funding Request

NY067	CSS# 91620 WO# 20626				
Description of Repairs	Labor and material to a.) remove the actuator and valve b.) install the new valve c.) reinstall the actuator and test for proper operation d.) replace the stained ceiling tile				
Diagnosis: Initial Work Order	Investigate leaking pump/water line that is above the drop ceiling on the lower level of the building.				
Diagnostic Fee	NA				
Additional Labor Cost to Perform Repairs	$6 \times \$80.00 = \480.00				
Additional Material Cost to Perform Repairs	<p>\$ 166.48</p> <table border="1" style="margin-left: 20px;"> <tr> <td>Materials (See attached detail)</td> <td>1</td> <td>166.48</td> <td>166.48</td> </tr> </table>	Materials (See attached detail)	1	166.48	166.48
Materials (See attached detail)	1	166.48	166.48		
Total Cost of Repair	\$ 646.48				

To:

TIDEWATER INC
6625 SELNICK DR #A
ELKRIDGE MD 21075-6220

Information

Date 01/25/2023
Customer Account Number 885295220
Grainger Quote Number 47658026
Customer Job Number
Contract Number
Grainger Representative John R Romano
Phone Number
Fax Number
Email
Grainger Tax ID 36-1150280

Item	Description Manufacturer Name & Model	Cat. Pg. #	Qty	\$ Quote	Ext. Price	Start Date	Exp. Date
41P854	Globe Valve,2-Way,NO,1/2 In,(F)NPT JOHNSON CONTROLS VG7241ET Country of Origin: Mexico		1	138.73	138.73	01/25/2023	05/31/2023
Total \$							138.73

All orders are subject to the terms and conditions in your current contract with Grainger or to Grainger's current Terms of Sale as set forth on Grainger.com

