

Additional Funding Request

NY013	CSS# 91758 WO# 21055				
Description of Repairs	Labor and material to a.) remove the pump that's not working b.) install a new pump and test for proper operation				
Diagnosis: Initial Work Order	HVAC Circulation pump is bad and will need to be replaced.				
Diagnostic Fee	NA				
Additional Labor Cost to Perform Repairs	$5 \times \$80.00 = \400.00				
Additional Material Cost to Perform Repairs	<p>\$ 573.78</p> <table border="1" style="margin-left: auto; margin-right: auto;"> <tr> <td>Materials (See attached detail)</td> <td>1</td> <td>573.78</td> <td>573.78</td> </tr> </table>	Materials (See attached detail)	1	573.78	573.78
Materials (See attached detail)	1	573.78	573.78		
Total Cost of Repair	\$ 973.78				

F.W. Webb Company
6792 Townline Road
Syracuse, NY 13211
TEL# (315-476-9322)
FAX# (315-472-4139)

Quote
Number
01/24/23
79390688

To:
TIDEWATER, INC.
6625 SELNICK DRIVE

TIDEWATER, INC.
6625 SELNICK DRIVE

ELKRIDGE MD 21075

ELKRIDGE MD 21075
PUMP

(410-540-8700) Fax# (410-579-1685)

Cust # Customer Po# Rel#
198314 PUMP / PAT BROWN

Writer Date Req
BTW 01/24/23
PAGE 1 OF 1

Quoted By: BRIAN WOLFORD

Quantity	Description	Net	Price	Exten	Ln#
1	* CIRC PMP SBRUTE XL UPS43-100 F 3 SPD GRU95906636 (419984) STOCK SYRACUSE	478.150	478.15	(1)	
		Sub Total:	478.15		
		Total:	478.15		

*** NUMBER OF DAYS QUOTE VALID IS 1 ***

PLEASE REFERENCE QUOTE # 79390688 FOR INQUIRIES OR ORDER OF ABOVE MATERIAL

GRUNDFOS.

NONSUBMERSIBLE CIRCULATION PUMP

TYPE: UPS43-100F
PC: P1 2111
P/N: 95906636



115V 60Hz 40UF
US ENC 2
1.75 (A) | P₁ (W) 2.5 | 265 -
3.1 | 335 =
3.5 | 370 ≡
MAX FLUID TEMP. 230 F
FOR INDOOR USE ONLY
PROTECTED
THERMALLY
CLASS H
3191277
INTERTEK
UL/CSA

