

CASTO TECHNICAL SERVICES, INC.

SERVICE REPORT

DATE 8-17-23 ARRIVAL TIME 7:30 DEPARTURE TIME 11:00 JOB/TCK NO 194258

DEPARTURE TIME 11:00 JOB/TICK NO 194258

JOB/TICK NO 194258

CUSTOMER PO. NO. CSS 92190 WO 12304

JOB NAME/LOCATION USARC - Morgantown WV029

SERVICE REQUESTED (10) Investment is labor and a scissor lift to repair the tube heater in the Motor Pool Wash Bay. NTE

Manufacture: _____
Model#: DTH-S-50-150 N3
Serial#: 4020863008100001

Refrigerant Added:	Qty	lb	oz	TYPE
Refrigerant Removed:	Qty	lb	oz	TYPE

Leak Tested
 Leak Found
 Leak Repaired

Method: _____

Total Charge: _____

WORK PERFORMED/UNIT INFO

WORK PERFORMANCE/UNIT INFO:

Diagnosing radiant heater in the wash bay for repairs. Once I moved equipment out of the way I turned power on to the unit and Started checking the system. I found that the first tube passed the igniter had a leak on the top of the tube which was blower out a blue flame. I got information and will send a quote in for repairs. Shut heater back down and put materials back where they were before leaving.

Quote will be sent

NATURE OF WORK

Regular Service _____

Quoted Service _____

Start-up/Warranty _____

SPD _____

Contract Service _____

Energy Management _____

PARTS, MATERIALS AND SUBCONTRACTED SERVICES

SUMMARY OF TIME

JOB COMPLETE YES NO EXPLAIN

SIGNATURE _____

Customer Representative