

## Additional Funding Request

<b>NY067</b>	<b>CSS# 93319 WO# 22135</b>			
Description of Repairs	Labor and material to a.) Repair-stained ceiling tiles: Repair leak. Room tag 015.			
Diagnosis: Initial Work Order	<b>Repair leak above ceiling</b>  <b>There is a stain on a tile above the stairway downstairs (Room tag 015).</b>  <b>There appears to be a slow drip of oil coming from above, possibly off a pump.</b>			
Diagnostic Fee	NA			
Additional Labor Cost to Perform Repairs	(10) hours x 100.00 = \$1000.00			
Additional Material Cost to Perform Repairs	<table border="1" style="width: 100%;"> <tr> <td style="width: 80%;">Materials (See attached detail)</td><td style="width: 20%; text-align: right;">\$75.00</td></tr> </table>		Materials (See attached detail)	\$75.00
Materials (See attached detail)	\$75.00			
Total Cost of Repair	\$ 1075.00			

**HUNOLD CONTRACTING INC.**

72 PENDERGAST ROAD

PHOENIX, NY 13135

Cell # 315-247-5898

Customer:

Tidewater Attn: Karlee

6625 Selmick Dr., Suite A

Elkridge, MD 21075

**ESTIMATE****5/3/23**

<b>Quantity</b>	<b>Description</b>	<b>Amount</b>
1	USARC Utica, NY. NY067 CSS 93319  Repair-stained ceiling tiles: Repair leak. Room tag 015.  Material: (Tiles/ leak containment/ assessment) \$75 Labor: (10 hours @ \$100/ hr.) \$1000  Price includes all labor, equipment and material.	<b>1075.00</b>
<b>Sub total</b>		<b>1075.00</b>
<b>Sales Tax</b>		<b>N/A</b>
<b>Total</b>		<b>1075.00</b>

Signature\_\_\_\_\_ Date\_\_\_\_\_

Signature\_\_\_\_\_ Date\_\_\_\_\_