

## Additional Funding Request

<b>NY051</b>	<b>CSS# 93545 WO# 22698</b>		
Description of Repairs	Labor and material to a.) Repair hot water leak near mechanical rooms. B.) Repair wet insulation and ceiling tiles using fittings, tiles and insulation		
Diagnosis: Initial Work Order	<b>Repair hot water supply line in ceiling. There is a hot water supply line in the hallway outside the mechanical room that is leaking onto the ceiling tile.</b>		
Diagnostic Fee	NA		
Additional Labor Cost to Perform Repairs	(8) hours x 100.00 = \$800.00		
Additional Material Cost to Perform Repairs	<table border="1"> <tr> <td>Materials (See attached detail)</td> <td>\$125.00</td> </tr> </table>	Materials (See attached detail)	\$125.00
Materials (See attached detail)	\$125.00		
Total Cost of Repair	\$ 925.00		

**HUNOLD CONTRACTING INC.**  
72 PENDERGAST ROAD  
PHOENIX, NY 13135  
Cell # 315-247-5898

Customer:

Tidewater Attn: Karlee  
6625 Selmick Dr., Suite A  
Elkridge, MD 21075

**ESTIMATE**  
**6/20/23**

<b>Quantity</b>	<b>Description</b>	<b>Amount</b>
1	USARC Oswego, NY. NY051 CSS 93545 WO 22698  Repair hot water leak near mechanical rooms. Repair wet insulation and ceiling tiles.   Material: (Fittings, tiles, insulation) \$125 Labor: (8 hours @ \$100/ hr.) \$800   Price includes all labor, equipment and material.	<b>925.00</b>
	<b>Sub total</b>	<b>925.00</b>
	<b>Sales Tax</b>	<b>N/A</b>
	<b>Total</b>	<b>925.00</b>

**Signature** \_\_\_\_\_ Date \_\_\_\_\_

**Signature** \_\_\_\_\_ Date \_\_\_\_\_

