

Additional Funding Request

NY127	CSS# 93636 WO# 22707						
Description of Repairs	Labor and material to a.) Repair rooftop atrium window section. b.) remove unit so glass factory can match replacement (Size, tint, thickness and glass quality.) c.) temporary material will be installed as it can take 2-3 weeks to have made. d.) Then install new unit. Daylight dimensions: 33 ¾" x 52 ¾" x 1". Please note: this will require 2 site visits.						
Diagnosis: Initial Work Order	Repair Window. The window at entrance foyer to ARC has cracked the full length of the pane.						
Diagnostic Fee	NA						
Additional Labor Cost to Perform Repairs	14 x 100.00 = \$1400.00						
Additional Material Cost to Perform Repairs	<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 50%;">Materials (See attached detail)</td><td style="width: 10%;">NA</td><td style="width: 20%;">928.00</td><td style="width: 20%;">928.00</td></tr> </table>			Materials (See attached detail)	NA	928.00	928.00
Materials (See attached detail)	NA	928.00	928.00				
Total Cost of Repair	\$ 2328.00						

HUNOLD CONTRACTING INC.

72 PENDERGAST ROAD

PHOENIX, NY 13135

Cell # 315-247-5898

Customer:

Tidewater Attn: Adam Colopy

6625 Selmick Dr., Suite A

Elkridge, MD 21075

ESTIMATE**7/12/23**

Quantity	Description	Amount
1	USARC Nichols, NY. NY127 CSS 93636 WO ?? Repair rooftop atrium window section. Will require two site visits. One to remove unit so glass factory can match replacement. Size, tint, thickness and glass quality. Temporary material will be installed as it can take 2-3 weeks to have made. Then install new unit. Daylight dimensions: 33 ¾" x 52 ¾" x 1". Material: (Sealed, low E, tempered unit) \$928 Labor: (14 hours @ \$100/ hr.) \$1400 Price includes all labor, equipment and material.	2328.00
Sub total		2328.00
Sales Tax		N/A
Total		2328.00

Signature_____ Date_____

Signature_____ Date_____

