

## Additional Funding Request

<b>NY067</b>	<b>CSS# 93692 WO# 22711</b>				
Description of Repairs	Labor and material to a.) repair ceiling exhaust OMS restrooms. b.) The exhaust fan supports both restrooms and needs to be replaced. This includes all associated wiring and duct work.				
Diagnosis: Initial Work Order	Ceiling Exhaust in OMS Restroom is not working.				
Diagnostic Fee	NA				
Additional Labor Cost to Perform Repairs	$16 \times \$100.00 = \$1600.00$				
Additional Material Cost to Perform Repairs	<p>\$ 248.00</p> <table border="1" style="margin-left: auto; margin-right: auto;"> <tr> <td>Materials (See attached detail)</td> <td>1</td> <td>248.00</td> <td>248.00</td> </tr> </table>	Materials (See attached detail)	1	248.00	248.00
Materials (See attached detail)	1	248.00	248.00		
Total Cost of Repair	\$ 1848.00				

**HUNOLD CONTRACTING INC.**  
72 PENDERGAST ROAD  
PHOENIX, NY 13135  
Cell # 315-247-5898

Customer:

Tidewater Attn: Karlee  
6625 Selmick Dr., Suite A  
Elkridge, MD 21075

**ESTIMATE**  
**5/3/23**

<b>Quantity</b>	<b>Description</b>	<b>Amount</b>
1	USARC Utica, NY. NY067 CSS 93292 WO 22711  Repair ceiling exhaust OMS restrooms. The exhaust fan supports both restrooms and needs to be replaced. This includes all associated wiring and duct work.  Material: (fan) \$248 Labor: (16 hours @ \$100/ hr.) \$1600  Price includes all labor, equipment and material.	<b>1848.00</b>
	<b>Sub total</b>	<b>1848.00</b>
	<b>Sales Tax</b>	<b>N/A</b>
	<b>Total</b>	<b>1848.00</b>

**Signature** \_\_\_\_\_ Date \_\_\_\_\_

**Signature** \_\_\_\_\_ Date \_\_\_\_\_













