

## Additional Funding Request

<b>NY127</b>	<b>CSS# 93981 WO# 23317</b>		
Description of Repairs	Labor and material to a.) Repair outlet for audio visual equipment, Room 103.		
Diagnosis: Initial Work Order	<b>Ceiling outlet in Learning center room 103 used for audio visual equipment is not working.</b>		
Diagnostic Fee	NA		
Additional Labor Cost to Perform Repairs	(6) hours x 100.00 = \$600		
Additional Material Cost to Perform Repairs	<table border="1" style="width: 100%;"> <tr> <td style="padding: 2px;">Materials (See attached detail)</td> <td style="padding: 2px;">\$9.00</td> </tr> </table>	Materials (See attached detail)	\$9.00
Materials (See attached detail)	\$9.00		
Total Cost of Repair	\$ 609.00		

**HUNOLD CONTRACTING INC.**  
72 PENDERGAST ROAD  
PHOENIX, NY 13135  
Cell # 315-247-5898

Customer:

Tidewater Attn: Karlee  
6625 Selmick Dr., Suite A  
Elkridge, MD 21075

**ESTIMATE**  
**6/20/23**

<b>Quantity</b>	<b>Description</b>	<b>Amount</b>
1	USARC Nichols, NY. NY127 CSS 93981 WO ??  Repair outlet for audio visual equipment. Room 103.   Material: (Outlet) \$9 Labor: (6 hours @ \$100/ hr.) \$600	<b>609.00</b>
	Price includes all labor, equipment and material.	
	<b>Sub total</b>	<b>609.00</b>
	<b>Sales Tax</b>	<b>N/A</b>
	<b>Total</b>	<b>609.00</b>

**Signature** \_\_\_\_\_ Date \_\_\_\_\_

**Signature** \_\_\_\_\_ Date \_\_\_\_\_