

Date: 12/1/2023

Region: 4C
FAC ID: WV029

CSS No.: 94866
Maximo WO No.: 14515

Asset #: NA

Priority: Routine



Original Work Request:

Repair high ceiling light in wash bay.

Description of Repairs Needed:

Labor and material to a.) replace the Lumens - 150 Watt - 5000 Kelvin - UFO LED High Bay Sensor Ready Light Fixture with Direct and Indirect Light and test for proper operation

Labor	Labor Hrs	Labor Rate	Total
Technician	8	\$ 100.00	\$ 800.00
		\$ -	\$ -

Material List:	Quantity	Cost	Total
Lumens - 150 Watt - 5000 Kelvin - UFO LED High Bay Sensor Ready Light Fixture with Direct and Indirect Light	1	\$ 126.12	\$ 126.12

Equipment List:	Quantity	Cost	Total
		\$ -	\$ -
		\$ -	\$ -
		\$ -	\$ -

PM WO History:

NA

Estimate Summary:

Labor	Material	Equipment
\$ 800.00	\$126.12	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$926.12	--	--	\$926.12

Note: G&A and Fee are not applied on top of work performed by Tidewater.



Prepared by:

Tidewater, Inc.
6625 Selkirk Drive, Suite A
Elkridge, MD 21075

Prepared for:

CMI Management, Inc.
5285 Shawnee Road Suite 510
Alexandria, VA 22312-2334

Date: 12/1/2023 CSS #: 94866
FAC ID: WV029 WO #: 14515

DESCRIPTION OF WORK			
Labor and material to a.) replace the Lumens - 150 Watt - 5000 Kelvin - UFO LED High Bay Sensor Ready Light Fixture with Direct and Indirect Light and test for proper operation			

LABOR	QTY	UNIT/RATE	TOTAL
Technician	8	\$100.00	\$800.00
		\$0.00	\$0.00
MATERIAL	QTY	UNIT/RATE	TOTAL
Lumens - 150 Watt - 5000 Kelvin - UFO LED High Bay Sensor Ready Light Fixture with Direct and Indirect Light	1	\$126.12	\$126.12
		\$0.00	\$0.00
		\$0.00	\$0.00
		\$0.00	\$0.00
		\$0.00	\$0.00
		\$0.00	\$0.00
EQUIPMENT	QTY	UNIT/RATE	TOTAL
		\$0.00	\$0.00
		\$0.00	\$0.00
		\$0.00	\$0.00
SUB-TOTAL COSTS:		LABOR TOTAL	\$800.00
		MATERIAL TOTAL	\$126.12
		EQUIPMENT TOTAL	\$0.00
TOTAL COST:			\$926.12

Accepted By: _____

Date: _____