

Date: 11/17/2023

Region: 4C  
FAC ID: WV009

CSS No.: 95103  
Maximo WO No.: 14495

Asset #: NA

Priority: Routine



**Original Work Request:**

Repair outside eye wash - leaking at fitting

**Description of Repairs Needed:**

Labor and material to a.) replace a 3/4" x 8" falv pipe nipple and test for proper operation.  
Please note that as we take off the water fountain we may find additional work that will need to be completed for this repair.

Labor	Labor Hrs	Labor Rate	Total
Technician	3	\$ 100.00	\$ 300.00
		\$ -	\$ -

Material List:	Quantity	Cost	Total
3/4" x 8" falv pipe nipple	1	\$ 8.24	\$ 8.24

Equipment List:	Quantity	Cost	Total
		\$ -	\$ -
		\$ -	\$ -
		\$ -	\$ -

**PM WO History:**

NA

**Estimate Summary:**

Labor	Material	Equipment
\$ 300.00	\$ 8.24	\$ 0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$308.24	--	--	\$308.24

Note: G&A and Fee are not applied on top of work performed by Tidewater.



Prepared by:

Tidewater, Inc.  
6625 Selkirk Drive, Suite A  
Elkridge, MD 21075

Prepared for:

CMI Management, Inc.  
5285 Shawnee Road Suite 510  
Alexandria, VA 22312-2334

Date: 11/17/2023 CSS #: 95103  
FAC ID: WV009 WO #: 14495

DESCRIPTION OF WORK			
Labor and material to a.) replace a 3/4" x 8" falv pipe nipple and test for proper operation. Please note that as we take off the water fountain we may find additional work that will need to be completed for this repair.			

LABOR	QTY	UNIT/RATE	TOTAL
Technician	3	\$100.00	\$300.00
		\$0.00	\$0.00
MATERIAL	QTY	UNIT/RATE	TOTAL
3/4" x 8" falv pipe nipple	1	\$8.24	\$8.24
		\$0.00	\$0.00
		\$0.00	\$0.00
		\$0.00	\$0.00
		\$0.00	\$0.00
		\$0.00	\$0.00
EQUIPMENT	QTY	UNIT/RATE	TOTAL
		\$0.00	\$0.00
		\$0.00	\$0.00
		\$0.00	\$0.00
SUB-TOTAL COSTS:	LABOR TOTAL		\$300.00
	MATERIAL TOTAL		\$8.24
	EQUIPMENT TOTAL		\$0.00
TOTAL COST:			\$308.24

Accepted By: \_\_\_\_\_

Date: \_\_\_\_\_

