


**DAILY TIME AND MATERIAL REPORT**JOB NAME: USAR

CUSTOMER NAME: \_\_\_\_\_

Fairview PA \_\_\_\_\_

FOR WORK PERFORMED ON 1-17-24 (DATE)**HOURS PER MAN**

NAME	CLASS	STRAIGHT	OVERTIME	DOUBLE TIME
Adam Wilkinson	Foreman	4		
	<b>TOTAL HOURS</b>	<b>4</b>		

**COMMENTS**

Found head in mailroom leaking at the seat. Most likely caused by freezing due to building not being insulated. Vary cold and possibly frozen piping found throughout due to no insulation or heat above ceiling where piping runs. Areas with wet system piping shall be maintained at or above 40 degrees per fire code. System left normal and in service.

**BUYER VERIFICATION AND ACCEPTANCE OF LABOR AND MATERIAL LISTED ABOVE.**

CONFERRED WITH: \_\_\_\_\_

DATE: 1-17-24