

Date: 2/7/2024

Region: 4C
FAC ID: WV046

CSS No.: 96639
Maximo WO No.: 15005

Asset #: NA

Priority: Urgent



Original Work Request:

The hot water pump on the hot water loop for the heat in the BMA shop is leaking and needs to be repaired with new seals. This repair needs to be done fairly quick so we don't lose heat in facility.

Description of Repairs Needed:

Labor and material to a.) to replace the 645-816707-005K Armstrong Seal Kit

Labor	Labor Hrs	Labor Rate	Total
Technician	10	\$ 100.00	\$ 1,000.00
		\$ -	\$ -

Material List:	Quantity	Cost	Total
645-816707-005K Armstrong Seal Kit	1	\$ 281.22	\$ 281.22
		\$ -	\$ -
		\$ -	\$ -
		\$ -	\$ -

Equipment List:	Quantity	Cost	Total
		\$ -	\$ -
		\$ -	\$ -
		\$ -	\$ -

PM WO History:

NA

Estimate Summary:

Labor	Material	Equipment
\$ 1,000.00	\$281.22	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$1,281.22	--	--	\$1,281.22

Note: G&A and Fee are not applied on top of work performed by Tidewater.



Prepared by:

Tidewater, Inc.
6625 Selknick Drive, Suite A
Elkridge, MD 21075

Prepared for:

CMI Management, Inc.
5285 Shawnee Road Suite 510
Alexandria, VA 22312-2334

Date: 2/7/2024 CSS #: 96639
FAC ID: WV046 WO #: 15005

DESCRIPTION OF WORK			
Labor and material to a.) to replace the 645-816707-005K Armstrong Seal Kit			

LABOR	QTY	UNIT/RATE	TOTAL
Technician	10	\$100.00	\$1,000.00
		\$0.00	\$0.00
MATERIAL	QTY	UNIT/RATE	TOTAL
645-816707-005K Armstrong Seal Kit	1	\$281.22	\$281.22
		\$0.00	\$0.00
		\$0.00	\$0.00
		\$0.00	\$0.00
		\$0.00	\$0.00
		\$0.00	\$0.00
EQUIPMENT	QTY	UNIT/RATE	TOTAL
		\$0.00	\$0.00
		\$0.00	\$0.00
		\$0.00	\$0.00
SUB-TOTAL COSTS:	LABOR TOTAL		\$1,000.00
	MATERIAL TOTAL		\$281.22
	EQUIPMENT TOTAL		\$0.00
TOTAL COST:			\$1,281.22

Accepted By: _____

Date: _____