

CASTO TECHNICAL SERVICES, INC.

SERVICE REPORT

DATE 2024 05 22 ARRIVAL TIME 8:00 DEPARTURE TIME 3:30 JOB/TCK. NO. 205441CUSTOMER P.O. NO. WO#15407 CSS97007JOB NAME/LOCATION USARC - South RidgeSERVICE REQUESTED (28) Labor to troubleshoot AHU-3 & 4, replace OAD on AHU-4, 7, and 8, and replace EF Motor.

Manufacture: _____				
Model#: _____				
Serial#: _____				
Refrigerant Added:	Qty	lb	oz	TYPE
Refrigerant Removed:	Qty	lb	oz	TYPE

☐ Leak Tested

☐ Leak Found

☐ Leak Repaired

Method: _____

Total Charge: _____

WORK PERFORMED/UNIT INFO.

Arrived on site, checked in with customer. Changed out Outdoor Air Damper actuator on AHU 7. Ensured it operated by driving mixed air dampers open and closed. Changed outdoor air damper actuator on AHU 8. Repeated process ensuring actuator was operating correctly. Investigated AHU 5 actuator and found it to be operating correctly. Checked out chiller and found alarm for low pressure differential. Will return tomorrow to continue work.

NATURE OF WORK

Regular Service _____

Quoted Service _____

Start-up/Warranty _____

SPD _____

Contract Service _____

Energy Management _____

PARTS, MATERIALS AND SUBCONTRACTED SERVICES

QTY.	PART NO.	DESCRIPTION	P.L.	VENDOR	
1		Damper Actuator		Belimo	241992
1		Damper actuator		Belimo	241992

SUMMARY OF TIME

SERVICE TECHNICIAN	ON SITE REG.	ON SITE O.T.	REG. TRAVEL	O.T. TRAVEL	TOTAL HRS.	MEALS	LODGING	TOLLS	MILES	OTHER
1307 Austin Roberts	7				7					

JOB COMPLETE YES _____ NO X EXPLAIN _____

SIGNATURE _____

Customer Representative