

CASTO TECHNICAL SERVICES, INC.

SERVICE REPORT

DATE 2024 5 23 ARRIVAL TIME 8:30

DEPARTURE TIME 4:00

JOBTICK NO. 205441

CUSTOMER PO. NO WO#15407 CSS97007

JOB NAME/LOCATION *USARC - South Ridge*

SERVICE REQUESTED (28) Labor to troubleshoot AHU-3 & 4, replace OAD on AHU-4, 7, and 8, and replace FF Motor

Manufacture: _____
Model#: _____
Serial#: _____
Refrigerant Added: Qty lb oz TYPE
Refrigerant Removed: Qty lb oz TYPE

- Leak Tested
- Leak Found
- Leak Repaired

Method: _____

Total Charge: _____

WORK PERFORMED/UNIT INFO

Arrived on site, checked in with customer. Changed out Outdoor Air Damper actuator on AHU 4. Ensured it operated by driving mixed air dampers open and closed.

on AHU 4. Ensured it operated by driving mixed air dampers open and closed. Investigated AHU 2 actuator and found it to be operating correctly. Checked AHU 6 OAD actuator and found the linkages were loose. Tightened those and ensured they operated. Chiller is now going out on alarm of Suction Temperature High on circuit 2. Sensor is reading 100 degrees with circuit 2 off. Can not get techview to work to hook up to chiller. will return to complete exhaust fan motor.

NATURE OF WORK

Regular Service _____

Quoted Service _____

Start-up/Warranty _____

SPD _____

Contract Service _____

Energy Management

PARTS, MATERIALS AND SUBCONTRACTED SERVICES

SUMMARY OF TIME

JOB COMPLETE

YES _____ NO EXPLAIN

SIGNATURE _____

Customer Representative