

SERVICE REPORT

DATE 2024 5 31 ARRIVAL TIME 10:00 DEPARTURE TIME 1:30 JOB/TCK. NO. 207222

CUSTOMER P.O. NO. CSS# 97228

JOB NAME/LOCATION *USARC - Rainelle WV035*

SERVICE REQUESTED (10) Investment is to perform an Annual PM on (1) Segmented Boiler. W/o 15414

Manufacture: <u>Burnham</u>				
Model#: <u>V9A/V11</u>				
Serial#: <u>123445</u>				
Refrigerant Added:	Qty	lb	oz	TYPE
Refrigerant Removed:	Qty	lb	oz	TYPE

☐ Leak Tested

☐ Leak Found

☐ Leak Repaired

Method: _____

Total Charge: _____

WORK PERFORMED/UNIT INFO.

Was already on site. I went through all the electrical connections. Then took the side panels off the boiler and looked for leaks in the gaskets between the sections. Then went and turned on the boiler and checked all the safeties. I then checked and made sure the pop off for the boiler was still good and it was. I then used a flue analyzer and took the low fire and high fire on the boiler. i did not have to clean the burner because i had already cleaned it when i was there on a service call where the boiler would not light. I then packed up tools and done paper work.

NATURE OF WORK

Regular Service _____
Quoted Service _____
Start-up/Warranty _____
SPD _____
Contract Service _____
Energy Management _____

PARTS, MATERIALS AND SUBCONTRACTED SERVICES

[illegible]

SUMMARY OF TIME

[illegible]

JOB COMPLETE YES X NO _____ EXPLAIN _____

SIGNATURE _____

Customer Representative