

Date: 8/1/2024

Region: 4C
FAC ID: WV029

CSS No.: 98520
Maximo WO No.: 16373

Asset #: NA

Priority: Routine



Original Work Request:

Repair water fountain downstairs in training building. Bottle filling area isn't putting out water.

Description of Repairs Needed:

Labor and material to a.) remove bad solenoid valve, b.) supply & install (1) Zurn Elkay 1000001622 Solenoid Valve 98466C for enhanced bottle fillers, c.) test for proper operation. Clean area and properly dispose of all spent materials.

Labor	Labor Hrs	Labor Rate	Total
Technician	6	\$ 100.00	\$ 600.00
		\$ -	\$ -

Material List:	Quantity	Cost	Total
Elkay 1000001622 Solenoid Valve 98466C	1	\$ 131.58	\$ 131.58
		\$ -	\$ -
		\$ -	\$ -
		\$ -	\$ -
		\$ -	\$ -
		\$ -	\$ -
		\$ -	\$ -

Equipment List:	Quantity	Cost	Total
		\$ -	\$ -
		\$ -	\$ -
		\$ -	\$ -

PM WO History:

NA

Estimate Summary:

Labor	Material	Equipment
\$600.00	\$131.58	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$731.58	--	--	\$731.58

Note: G&A and Fee are not applied on top of work performed by Tidewater.



Prepared by:

Tidewater, Inc.
6625 Selkirk Drive, Suite A
Elkridge, MD 21075

Prepared for:

CMI Management, Inc.
5285 Shawnee Road Suite 510
Alexandria, VA 22312-2334

Date: 8/1/2024 CSS #: 98520
FAC ID: WV029 WO #: 16373

DESCRIPTION OF WORK			
Labor and material to a.) remove bad solenoid valve, b.) supply & install (1) Zurn Elkay 1000001622 Solenoid Valve 98466C for enhanced bottle fillers, c.) test for proper operation. Clean area and properly dispose of all spent materials.			

LABOR	QTY	UNIT/RATE	TOTAL
Technician	6	\$100.00	\$600.00
		\$0.00	\$0.00
MATERIAL	QTY	UNIT/RATE	TOTAL
Elkay 1000001622 Solenoid Valve 98466C	1	\$131.58	\$131.58
		\$0.00	\$0.00
		\$0.00	\$0.00
		\$0.00	\$0.00
		\$0.00	\$0.00
		\$0.00	\$0.00
EQUIPMENT	QTY	UNIT/RATE	TOTAL
		\$0.00	\$0.00
		\$0.00	\$0.00
		\$0.00	\$0.00
SUB-TOTAL COSTS:	LABOR TOTAL		\$600.00
	MATERIAL TOTAL		\$131.58
	EQUIPMENT TOTAL		\$0.00
TOTAL COST:			\$731.58

Accepted By: _____

Date: _____