

Date: 9/18/2024

Region: 4A

FAC ID: NY070

CSS No.: 98580

Maximo WO No.: 16355

Asset #: NA

Priority: Routine



Original Work Request:

Repair the hot water tank exhaust pipe. When the hot water tank does a pre-purge of the gas before it starts the natural gas is coming back into the building through the intake pipe. Exhaust pipe will need to be extended to prevent any unused natural gas from coming back into the building.

Description of Repairs Needed:

Labor and material to a.) repair/ extend hot water pipes, b.) supply and install approximately 30' - 4" scheduled 40 PVC pipe, 2 - 4" schedule 40 elbows, and 6 - 4" schedule 40 couplings.

Labor:	Labor Hrs	Labor Rate	Total
Technician	7	\$ 100.00	\$ 700.00
			\$ -

Material List:	Quantity	Cost	Total
30' - 4" schdule 40 PVC pipe, 2 - 4" schedule 40 elbows, 6 - 4" schedule 40 couplings	1	\$ 249.00	\$ 249.00
			\$ -
			\$ -
			\$ -

Equipment List:	Quantity	Cost	Total
			\$ -
			\$ -
			\$ -

PM WO History:

NA

Estimate Summary:

Labor	Material	Equipment
\$ 700.00	\$ 249.00	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$949.00	\$113.88	\$56.94	\$1,119.82

HUNOLD CONTRACTING INC.

72 PENDERGAST ROAD

PHOENIX, NY 13135

Cell # 315-247-5898

Customer:

Tidewater Attn: JuliePape

6625 Selmick Dr., Suite A

Elkridge, MD 21075

ESTIMATE**9/18/24**

Quantity	Description	Amount
1	CSS 98580, WO 16355, NY070 Webster, NY Repair/ extend hot water vent pipes. Material: (\$249) 30'- 4" schedule 40 PVC pipe 2- 4" schedule 40 elbows 6- 4" schedule 40 couplings Labor: (7 hours @ \$100/ hr.) =\$700	949.00
Sub total		949.00
Sales Tax		N/A
Total		949.00

Signature_____ Date_____

Signature_____ Date_____