

Date: 9/9/2024



Region: 4C

CSS No.: 98882

FAC ID: WV022

Maximo WO No.: 16630

Asset #: NA

Priority: Routine

Original Work Request:

Repair exterior light above drill hall door - training building. Will need a lift to complete this job.

Description of Repairs Needed:

Labor and material to a.) replace (1) LEDV AREAFLD6AS300UNHDSC2T3BZ exterior light above drill hall door, training building, b.) test for proper operation.

Labor:	Labor Hrs	Labor Rate	Total
Technician	4	\$ 120.00	\$ 480.00
2nd Technician	4	\$ 100.00	\$ 400.00

Material List:	Quantity	Cost	Total
LEDV AREAFLD6AS300UNHDSC2T3BZ Light	1	\$ 500.00	\$ 500.00
			\$ -
			\$ -
			\$ -

Equipment List:	Quantity	Cost	Total
Lift Rental	1	\$ 700.00	\$ 700.00
			\$ -
			\$ -

PM WO History:

NA

Estimate Summary:

Labor	Material	Equipment
\$ 880.00	\$ 500.00	\$700.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$2,080.00	\$249.60	\$124.80	\$2,454.40



43 Pine Tree LN
Morgantown, WV 26508
(681) 270-0607
nselectricoffice@gmail.com

Estimate

ESTIMATE#	1050730655
DATE	09/04/2024
PO#	CSS 98882 WO16630 WV022

CUSTOMER

TIDEWATER, INC.
Julie Pape
6625 Selnick Drive
Elkridge, MD 21075
(904) 465-1981

SERVICE LOCATION

TIDEWATER, INC.
Julie Pape
Base
504 North Preston Hwy
Kingwood, WV 26537
(904) 465-1981

DESCRIPTION

Repair exterior light above drill hall door - training building. Will need a lift to complete this job.

Estimate

Description	Qty	Rate	Total
Labor Per 2 Tech	4.00	220.00	880.00
Rent Equipment	1.00	700.00	700.00
LEDV AREAFLD6AS300UNHDSC2T3BZ	1.00	500.00	500.00
Sales		6.000%	0.00

CUSTOMER MESSAGE

Estimate Total: \$2,080.00

PRE-WORK SIGNATURE

Signed By: