

Date: 12/2/2024



Region: 4C

CSS No.: 98978

FAC ID: WV029

Maximo WO No.: 16885

Asset #: NA

Priority: Routine

**Original Work Request:**

Repair 2 lights. One is high pole light in MP that flashes at night (strobing) and one wall pack on the corner of the Training Center facing the MP that is on but very, very dull. Will need a lift. Wall pack being addressed on CSS 98340.

**Description of Repairs Needed:**

Labor and material to a.) Supply and replace (1) high pole lights b.) test for proper operation, c.) clean area and properly dispose of all spent materials at job site.

Labor:	Labor Hrs	Labor Rate	Total
Electrician	2	\$ 120.00	\$ 240.00
Apprentice	2	\$ 100.00	\$ 200.00

Material List:	Quantity	Cost	Total
LEDV AREAFLD6AS300UNHDSC2T3BZ	1	\$ 500.00	\$ 500.00
			\$ -
			\$ -
			\$ -

Equipment List:	Quantity	Cost	Total
Lift rental	1	\$ 700.00	\$ 700.00
			\$ -
			\$ -

**PM WO History:**

NA
----

**Estimate Summary:**

Labor	Material	Equipment
\$ 440.00	\$ 500.00	\$ 700.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$1,640.00	\$196.80	\$98.40	\$1,935.20



43 Pine Tree LN  
Morgantown, WV 26508  
(681) 270-0607  
nselectricoffice@gmail.com

## Estimate

ESTIMATE#	1054683413
DATE	11/04/2024
PO#	CSS 98978 WO16885 WV029

### CUSTOMER

TIDEWATER, INC.  
Julie Pape  
6625 Selnick Drive  
Elkridge , MD 21075  
(904) 465-1981

### SERVICE LOCATION

TIDEWATER, INC.  
Julie Pape  
US Army Reserves  
228 Comfort Inn Rd  
Morgantown, West Virginia 26508-3501  
(904) 465-1981

### DESCRIPTION

SOW: Repair 2 lights. One is high pole light in MP that flashes at night (strobing) and one wall pack on the corner of the Training Center facing the MP that is on but very, very dull. Will need a lift.

## Estimate

Description	Qty	Rate	Total
Electrician Labor	2.00	120.00	240.00
Apprentice Labor	2.00	100.00	200.00
Equipment Rental	1.00	700.00	700.00
LEDV AREAFLD6AS300UNHDSC2T3BZ	1.00	500.00	500.00
Sales		6.000%	0.00

### CUSTOMER MESSAGE

**Estimate Total: \$1,640.00**

### PRE-WORK SIGNATURE

Signed By: