

Date: 3/5/2025

Region: 4C
FAC ID: WV010

CSS No.: 99083
Maximo WO No.: 16920

Asset #: NA

Priority: Routine



Original Work Request:

Repair OMS exit sign, OMS eyewash in battery room, and OMS emergency lights.

Description of Repairs Needed:

Labor and material to a.) will need to isolate the eyewash station, b.) disassemble the bowl and eyewash valve, c.) furnish and install (1) new valve and bowl assembly, c.) will need to remove the exit signs, d.) furnish and install (4) new exit signs, e.) remove emergency lights that are not functioning properly, f.) furnish and install (4) new emergency lights in OMS, g.) test for proper operation, h.) clean up and properly dispose of all spent materials.

Labor	Labor Hrs	Labor Rate	Total
Tidewater Technician	13	\$ 100.00	\$ 1,300.00
		\$ -	\$ -

Material List:	Quantity	Cost	Total
Plumbed Eyewash, Eyes & Face Coverage, Covered, Push Plate 2LVJ5	1	\$ 979.06	\$ 979.06
Exit Sign, Emergency Battery Backup, LED White, Red 32WU26	4	\$ 133.45	\$ 533.80
Emergency Light, LED Damp location rated, 2.5W, 120/277V AC, 19L031	4	\$ 92.74	\$ 370.96
Nipple, galvanized steel, 1/2" pipe size, 2 1/2" Overall Lg. Threaded both ends NPT 6P790	1	\$ 4.02	\$ 4.02
		\$ -	\$ -
		\$ -	\$ -

Equipment List:	Quantity	Cost	Total
		\$ -	\$ -
		\$ -	\$ -
		\$ -	\$ -

PM WO History:

NA

Estimate Summary:

Labor	Material	Equipment
\$1,300.00	\$1,887.84	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$3,187.84	--	--	\$3,187.84

Note: G&A and Fee are not applied on top of work performed by Tidewater.



Prepared by:

Tidewater, Inc.
6625 Selkirk Drive, Suite A
Elkridge, MD 21075

Prepared for:

CMI Management, Inc.
5285 Shawnee Road Suite 510
Alexandria, VA 22312-2334

Date: 3/5/2025 CSS #: 99083
FAC ID: WV010 WO #: 16920

DESCRIPTION OF WORK

Labor and material to a.) will need to isolate the eyewash station, b.) disassemble the bowl and eyewash valve, c.) furnish and install (1) new valve and bowl assembly, c.) will need to remove the exit signs, d.) furnish and install (4) new exit signs, e.) remove emergency lights that are not functioning properly, f.) furnish and install (4) new emergency lights in OMS, g.) test for proper operation, h.) clean up and properly dispose of all spent materials.

LABOR	QTY	UNIT/RATE	TOTAL
Tidewater Technician	13	\$100.00	\$1,300.00
		\$0.00	\$0.00
MATERIAL	QTY	UNIT/RATE	TOTAL
Plumbed Eyewash, Eyes & Face Coverage, Covered, Push Plate 2LVJ5	1	\$979.06	\$979.06
Exit Sign, Emergency Battery Backup, LED White, Red 32WU26	4	\$133.45	\$533.80
Emergency Light, LED Damp location rated, 2.5W, 120/277V AC, 19L031	4	\$92.74	\$370.96
Nipple, galvanized steel, 1/2" pipe size, 2 1/2" Overall Lg. Threaded both ends NPT 6P790	1	\$4.02	\$4.02
		\$0.00	\$0.00
		\$0.00	\$0.00
EQUIPMENT	QTY	UNIT/RATE	TOTAL
		\$0.00	\$0.00
		\$0.00	\$0.00
		\$0.00	\$0.00
SUB-TOTAL COSTS:	LABOR TOTAL		\$1,300.00
	MATERIAL TOTAL		\$1,887.84
	EQUIPMENT TOTAL		\$0.00
TOTAL COST:			\$3,187.84

Accepted By: _____

Date: _____

