

Date: 8/17/2023

Region: 4A
FAC ID: NY126

CSS No.: 94651
Maximo WO No.: 13642



Asset #: NA

Priority: Routine

Original Work Request:

Replace contactor for motor #2 on chiller.

Description of Repairs Needed:

Labor and material to a.) replace the bad contactor for compressor 2 b.) wire in and test for proper operation.

NOTE: We will submit a recommendation for a follow up CSS Ticket, if further repairs are found/needed.

Labor:

	Labor Hrs	Labor Rate	Total
Technician	3	\$ 115.00	\$ 345.00
			\$ -

Material List:

	Quantity	Cost	Total
Contactor	1	\$ 718.20	\$ 718.20
Trip Charge	1	\$ 98.00	\$ 98.00
			\$ -
			\$ -

Equipment List:

	Quantity	Cost	Total
			\$ -
			\$ -
			\$ -

PM WO History:

NA

Estimate Summary:

Labor	Material	Equipment
\$ 345.00	\$ 816.20	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$1,161.20	\$139.34	\$69.67	\$1,370.22

Job Quote



Number: 36022

35 Bermar Park
Rochester, NY 14624

Quote Date: 8/3/2023

(585) 209-1600 (585) 209-1603 (fax)

Bill to: US Army Corp Reserve Base
49 Jetview Drive
Rochester, NY 14624

Service at: US Army Corp Reserve Base
49 Jetview Drive
Rochester, NY 14624

Customer ID: 12337

Description: On McQuay chiller replace bad contactor for compressor 2 so compressor will run. Wire in and test system.

Equipment Details

Manufacturer: McQuay

Serial #: STNU1Z0100063

Model #: 96Z090DHHNN-ER10

Items	Quantity	Unit	Unit Price	Total Price
Service Labor	3.00		\$115.00	\$345.00
Contactor	1.00		\$718.20	\$718.20
Trip Charge	1.00		\$98.00	\$98.00

Quote Subtotal:	\$1,161.20
Estimated Tax:	\$0.00
Quote Amount:	\$1,161.20

Additional Details:

Authorized Signature

NOTE: Applicable sales tax will be added to the amount shown when the job is billed.