

Date: 11/20/2023

Region: 4C
FAC ID: WV022

CSS No.: 95303
Maximo WO No.: 14497

Asset #: NA

Priority: Routine



Original Work Request:

Repair by replacing 4 outside wall pack lights on motor pool building. Will require a lift.

Description of Repairs Needed:

Labor and material to a.) replace 2 outside wall packs and to parking lot lights

Labor:	Labor Hrs	Labor Rate	Total
Technician 2 Man Crew	8	\$ 220.00	\$ 1,760.00

Material List:	Quantity	Cost	Total
LED Wall Pack	2	\$ 185.45	\$ 370.90
Parking Lot Lights	2	\$ 312.45	\$ 624.90
			\$ -
			\$ -
			\$ -
			\$ -

Equipment List:	Quantity	Cost	Total
Bucket Truck	8	\$ 45.00	\$ 360.00
			\$ -
			\$ -

PM WO History:

NA

Estimate Summary:

Labor	Material	Equipment
\$1,760.00	\$995.80	\$360.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$3,115.80	\$373.90	\$186.95	\$3,676.64



43 Pine Tree LN
Morgantown, WV 26508
(681) 270-0607
nselectricoffice@gmail.com

Estimate

ESTIMATE#	1032146628
DATE	10/05/2023
PO#	

CUSTOMER

TIDEWATER, INC.
Karlee Demain
6625 Selnick Drive
Elkridge, MD 21075
(724) 678-6067
(410) 540-8700

SERVICE LOCATION

TIDEWATER, INC.
Karlee Demain
Billing
6625 Selnick Drive
Elkridge, MD 21075
(724) 678-6067
(410) 540-8700

DESCRIPTION	Replacing 2 outside wall packs and to parking lot lights
-------------	--

Estimate

Description	Qty	Rate	Total
Labor Per 2 technicians	220.00	8.00	1,760.00
Bucket truck	45.00	8.00	360.00
LED Wall Pack	2.00	185.45	370.90
Parking Lot Lights	2.00	312.45	624.90
Sales		6.00%	0.00

CUSTOMER MESSAGE

Estimate Total: \$3,115.80

PRE-WORK SIGNATURE

Signed By: