

## SERVICE REPORT

DATE 3-20-19

ARRIVAL TIME

DEPARTURE TIME

JOB/TCK. NO. 157388

CSS#14647

**JOB NAME/LOCATION** USARC - Lewisburg

**SERVICE REQUESTED** *Investment is 16 hrs of labor and mileage to leak check two Daikin VRF systems located at USARC Lewisburg, WV024, CSS #14647.*

Manufacture: <u>Daikin</u>				
Model#: <u>REMQ72PATJ</u>				
Serial#: <u>A000298</u>				
Refrigerant Added:	Qty	lb	oz	TYPE
Refrigerant Removed:	Qty	lb	oz	TYPE

☐ Leak Tested

☐ Leak Found

☐ Leak Repaired

Method: \_\_\_\_\_

Total Charge: \_\_\_\_\_

**WORK PERFORMED/UNIT INFO.**

Arrived on site, checked in with customer. Went through all of the rooms to see where every ceiling unit was to get a head count. Leak checked lines in the storage room, Found that the fittings where installed wrong and that they were all leaking. Went outside to leak check unit. Tried to do an acid test on unit but the unit was flat on gas. Hooked gauges up to make sure the unit was flat. Called Nate L. he said to get all of the serial and model numbers from every unit plus every heads to the units. Also drew up building layout and took measurements of building for print. told client we were done, cleaned up tools and mess.

### NATURE OF WORK

Regular Service \_\_\_\_\_

**Quoted Service** \_\_\_\_\_

**Start-up/Warranty** \_\_\_\_\_

SPD \_\_\_\_\_

**Contract Service** \_\_\_\_\_

Energy Management \_\_\_\_\_

## PARTS, MATERIALS AND SUBCONTRACTED SERVICES

[illegible]

### SUMMARY OF TIME

[illegible]

JOB COMPLETE YES \_\_\_\_\_ NO \_\_\_\_\_ EXPLAIN \_\_\_\_\_

**SIGNATURE** \_\_\_\_\_

**Customer Representative**