

## Richard Hicks

---

**From:** Richard Hicks  
**Sent:** Wednesday, July 14, 2021 12:21 PM  
**To:** Mary Lowery; Lindsay Ruby; Gabrielle Mascelli; Adam Colopy  
**Cc:** Augustin, Kenneth P CIV USARMY 99 RD (USA); Jason D CTR USARMY 99 RSC (USA) Gavin  
**Subject:** DE007 WO# 14543 Please update your trackers ON-HOLD

Lindsay , Gabby , Mary ,  
I spoke with Ken they will want this actioned later in the future . SO for now move the diagnostic fee to the other DE007 work orders and I will put this one ON- HOLD in Maximo to address next Option year 4 in October due to funding.

Thanks,  
Rick

Rick Hicks  
Project Manager Region 5  
CMI Management Inc.  
5285 Shawnee Road Suite #510  
Alexandria,VA 22312  
703-738-5301  
Richard.Hicks@cmimgmt.com

---

**From:** Mary Lowery <Mary.Lowery@tideh2o.net>  
**Sent:** Wednesday, July 14, 2021 11:51 AM  
**To:** Lindsay Ruby <lindsay@sandsmidatlantic.com>; Gabrielle Mascelli <gabrielle.mascelli@tideh2o.net>; Adam Colopy <adam.colopy@tideh2o.net>  
**Cc:** Richard Hicks <richard.hicks@cmimgmt.com>  
**Subject:** RE: DE007 WO# 14543

Thanks Lindsay- let me see what ricks thoughts are on this.

Thank you,  
**Mary Lowery**  
*Project Coordinator*  
**TIDEWATER, INC.**

---

[mary.lowery@tideh2o.net](mailto:mary.lowery@tideh2o.net)  
6625 Selnick Drive, Suite A  
Elkridge, MD 21075

C: 410-967-5346

---

**From:** Lindsay Ruby <[lindsay@sandsmidatlantic.com](mailto:lindsay@sandsmidatlantic.com)>  
**Sent:** Wednesday, July 14, 2021 11:48 AM  
**To:** Mary Lowery <[Mary.Lowery@tideh2o.net](mailto:Mary.Lowery@tideh2o.net)>; Gabrielle Mascelli <[gabrielle.mascelli@tideh2o.net](mailto:gabrielle.mascelli@tideh2o.net)>; Adam Colopy

<[adam.colopy@tideh2o.net](mailto:adam.colopy@tideh2o.net)>

**Subject:** DE007 WO# 14543

CAUTION: External email, DO NOT click on any links/attachments unless you recognize the sender and know the content is safe

Mary,

Let me know how you would like to proceed

Work Note for WO# 14543

found light pole that was out in rear of building near the transformer pad.

the pole has power to it. so the problem is up in the light. looks like it's a 400watt HP bulb and ballast could be bad. would have to get a 35' articulating light to reach light head.

talked with Jason and he would rather wait for more of the lights to go out to replace this due to having a lift delivered for just one light.

--

**Lindsay Ruby**

**S&S Mechanical**

*"Feeling Good About What We Do"*

**Phone:** 301-574-1555

**Fax:** 301-574-1558

[www.sandsmidatlantic.com](http://www.sandsmidatlantic.com)

[lindsay@sandsmidatlantic.com](mailto:lindsay@sandsmidatlantic.com)