

Additional Funding Request

Submitted: 7/8/20

DE007– boiler	CSS #25176 WO# 12442																			
Description of Repairs	-12315 -12442 Additional efforts needed for boiler repairs. Adjustment screw requires replacement.																			
Original SC Investigative Diagnosis	N/A																			
Diagnosis: Initial Work Order	<p>S&S proposes to remove and replace the air plate adjustment screw on the boiler.</p> <p>S&S will then complete a system check to ensure everything is running properly.</p>																			
Explanation of Additional Costs for Repairs	N/A																			
Additional Material Cost to Perform Repairs	<p>Materials: \$27.60</p> <table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="text-align: left;">ITEM</th><th style="text-align: center;">QUANTITY</th><th style="text-align: center;">UNIT PRICE</th><th style="text-align: center;">TOTAL</th></tr> </thead> <tbody> <tr> <td>Air Plate Adjustment Screw/ 5-20-000601</td><td style="text-align: center;">1</td><td style="text-align: center;">\$25.20</td><td style="text-align: center;">\$25.20</td></tr> <tr> <td>External Star Washer</td><td style="text-align: center;">1</td><td style="text-align: center;">\$2.40</td><td style="text-align: center;">\$2.40</td></tr> <tr> <td></td><td></td><td></td><td></td></tr> </tbody> </table>				ITEM	QUANTITY	UNIT PRICE	TOTAL	Air Plate Adjustment Screw/ 5-20-000601	1	\$25.20	\$25.20	External Star Washer	1	\$2.40	\$2.40				
ITEM	QUANTITY	UNIT PRICE	TOTAL																	
Air Plate Adjustment Screw/ 5-20-000601	1	\$25.20	\$25.20																	
External Star Washer	1	\$2.40	\$2.40																	
Additional Labor Cost to Perform Repairs	<p>Labor: \$1,000.00</p> <p>Plumber Labor Tech/10 hours/Rate \$100.00 per hour = \$1,000.00</p>																			
Total Cost of Repair	\$1027.60																			